

International Boundary Commission,
United States and Canada

Joint Annual Report

2017

Maintaining a Peaceful Boundary for more than a Century

Photo de couverture



La photo de couverture montre la vue vers le sud à partir de la borne 9 sur le 141e méridien (Yukon/Alaska). La borne 9 est située environ à 298 km au nord du cercle polaire arctique et 42 km au sud de la mer de Beaufort.

**International Boundary Commission
Joint Annual Report 2017**



**International
Boundary
Commission**



**Commission
de la frontière
internationale**



**The Honorable Mike Pompeo
The Secretary of State for the United States
Washington, D.C.**

**The Honorable Chrystia Freeland
Minister of Foreign Affairs
Ottawa**

Mr. Pompeo, Ms. Freeland:

We have the pleasure of delivering to you the 93rd Joint Annual Report of the International Boundary Commission covering the work of the Commission in calendar year 2017.

The Treaty of Washington, 1925, mandated the Commissioners to maintain the boundary between the United States and Canada through the building, maintaining and moving of boundary monuments and buoys and through keeping the boundary vista clear with the goal of maintaining an effective boundary between our two countries.

We are happy to report that we have met these objectives through series of projects spread across the entire length of the boundary from Passamaquoddy Bay in the east to the shores of the Arctic Ocean in the north. You will find within this report summaries of the projects undertaken and detailed lists of the monuments that were built or maintained.

Respectfully submitted,

**Kyle K. Hipsley
Commissioner for the United States**

United States
1717 H Street N.W.
Suite 845
Washington, DC
20006 U.S.A.

Tel: (202) 736-9100
Fax: (202) 632-2008

**Jean Gagnon
Commissioner for Canada**

Canada
588 rue Booth Street
Room/bureau 210
Ottawa, Canada
K1A 0Y7

Tel/Tél: (613) 808-2756
Fax/Télécopieur: (613) 947-1337

TABLE OF CONTENTS

EXECUTIVE SUMMARY	1
INTRODUCTION.....	3
The Mandate of the Commissioners.....	3
MAINTENANCE ACTIVITIES	4
Passamaquoddy Bay (NB/ME) – Range Mark Maintenance.....	5
St. John River (NB/ME) – Reference Monument Maintenance	5
Southwest Branch of the St. John River (QC/ME) – Survey	5
Highlands N.E. Section (QC\ME) – Survey and Inspection.....	6
Highlands S.W. Section (QC\ME) – Vista Clearing and Inspection.....	6
West Line (QC/VT) – Monument Maintenance and Inspection	7
Lake Superior to Rainy River (ON/MN) – Reference Monument Maintenance	7
Rainy River and Lake of the Woods (ON/MN) – Reference Monument Maintenance	7
49 th Parallel (AB-SK-MB/MT- ND) – Vista clearing	8
Southeast Alaska (BC/AK) – Vista Clearing	8
141st Meridian (YK\AK) – Survey.....	8
Miscellaneous	9
COMMISSIONERS ACTIVITIES.....	11
Field inspections	11
REGULATORY ITEMS.....	12
PLANNING FOR 2018.....	13
ACCOMPLISHMENTS AGAINST THE 15-YEAR PLAN	14
REPORT ON COMPARABLE EXPENDITURES	15
COMMISSIONERS OF THE IBC	17
OBITUARY.....	18
CERTIFICATION.....	19
APPENDIX A – DETAILS OF MAINTENANCE AND SURVEY WORK.....	21
APPENDIX B – SUMMARY OF MAINTENANCE AND SURVEY WORK	77
APPENDIX C – 15 YEAR PLAN	81
APPENDIX D – PLANS OF MONUMENTS INSTALLED	91

EXECUTIVE SUMMARY

This is the 93rd Joint Annual Report of the Canadian and United States Commissioners to their respective governments on the state of the Canada/U.S. boundary. The International Boundary Commission (IBC) is a joint U.S./Canada organization with a mandate stretching back to the 1925 Treaty of Washington to maintain an effective boundary line through the maintenance of existing monuments, the positioning of new monuments where required, the clearing of the boundary vistas where appropriate and the surveying, mapping and publishing of accurate geodetic coordinates for the points that define the boundary.

To these ends, this year the IBC undertook projects that improved the visibility of the boundary on Passamaquoddy Bay, brought more of the Commission's official digital definition of the boundary into line with today's GPS technology both along the Alaska/Yukon boundary and in the highlands between Quebec and Maine/Vermont, cleared overgrown sections of the boundary of brush between Alberta and Montana and repaired or rebuilt existing ones in the Lake of the Woods/Boundary Waters section. The IBC also responded to specific requests from stakeholders for clearing short sections of the vista and improving marking at specific locations.

The IBC structures its maintenance work through a 15-year plan. That plan was updated this year to take into account new technologies and new requirements while still respecting the realities of the hard work of brush clearing, the construction of monuments in hard to reach places and the requirement for up-to-date maps and data that make the exact location of the boundary easily accessible to all. The IBC has an ongoing consultation with stakeholders to ensure our work supports the requirements of those with an interest in the boundary.

The work of the Commission is shared equally by the U.S. and Canadian sections of the IBC. The two sections share a common web site, a common Geographic Information System (GIS) and jointly produce data sets, maps and reports.

The Commissioners are pleased to report that the work of maintaining the boundary is proceeding according to plan and the condition of the boundary meets with the requirements of both countries.



Kyle K. Hipsley, Commissioner for the United States



Jean Gagnon, Commissioner for Canada

**International Boundary Commission
Joint Annual Report 2017**

INTRODUCTION

The boundary between Canada and the United States was defined and refined through a series of twenty six treaties, conventions, protocols, decisions and awards beginning with the 1783 *Treaty of Peace* and culminating in the 1925 *International Boundary Treaty*. In 1794 the first Commissioners were appointed to resolve ambiguities regarding the exact location of the boundary. The tradition of appointing Commissioners to resolve specific issues was carried on until, in the Treaty of 1925, the positions were made permanent and the Commissioners tasked with the ongoing maintenance of the boundary.

The Mandate of the Commissioners

The Treaty of 1925 set out the responsibilities of the Commissioners as:

1. Inspect the various sections of the boundary line between the Dominion of Canada and the United States and between the Dominion of Canada and Alaska at such times as they shall deem necessary;
2. Repair all damaged monuments and buoys;
3. Relocate and rebuild monuments which have been destroyed;
4. Keep the boundary vistas open;
5. Move boundary monuments to new sites and establish such additional monuments and buoys as they shall deem desirable;
6. Maintain at all times an effective boundary line between the Dominion of Canada and the United States;
7. Determine the location of any point of the boundary line which may become necessary in the settlement of any question that may arise between the two Governments.

The Commissioners were further instructed to submit to their respective Governments from time to time, at least once in every calendar year, a joint report containing a statement of the inspections made, the monuments and buoys repaired, relocated, rebuilt, moved, and established and the mileage and location of vistas opened. The report is to contain plats and tables certified and signed by the Commissioners, giving the locations and geodetic positions of all monuments moved and all additional monuments established within the year, and such other information as may be necessary to keep the boundary maps and records accurately revised.

This is the 93rd Joint Annual Report from the Commissioners to their respective Governments on the state of the Canada / US boundary.

MAINTENANCE ACTIVITIES

The 2017 field season began in May and ended in October. The Commission conducted projects in support of its 15 Year Maintenance Plan as well projects that advanced its goal of upgrading the geodetic coordinates that define the boundary.

To ensure efficient and orderly management of boundary maintenance activities, the boundary is split into 8 sections and 30 sub sections corresponding to areas with homogeneous characteristics. Projects are presented by sub sections and activity from East, to West, to North. A description of sub sections can be found on the IBC website¹.



¹ <http://internationalboundarycommission.org/en/maps-coordinates/maps/section-a.php>

Passamaquoddy Bay (NB/ME) – Range Mark Maintenance



The Passamaquoddy Bay section of the international boundary is delimited by turning points tied to a series of Range Marks. These are large, brightly painted monuments on shore that come in pairs. This year's contract was to clear the bush in front of the markers and to repaint the markers to ensure that they were easily visible from the water. An inspection after the work was completed showed this section of the boundary to be in very good condition.

Figure 1: A Range Mark on
Passamaquoddy Bay

St. John River (NB/ME) – Reference Monument Maintenance

This project continues the work done last year along the St. Francis River. This year the Reference Monuments along the St. John River were located, painted and repaired. When repairs were required the crew used traditional survey methods to ensure the Reference Monuments were rebuilt in their original locations thus ensuring the integrity of the boundary which runs down the St. John River.



Figure 2: Cleaning and painting a Reference Monument

Southwest Branch of the St. John River (QC/ME) – Survey



This project completes the resurveying and spatial reference update of the Southwest Branch of the St. John River. In this project, the final three Reference Monuments that define this section of the boundary were geolocated with a high precision GPS survey and tied into the NAD83 datum. These three monuments had either been destroyed and subsequently replaced, or there was insufficient survey information collected previously to determine their coordinates on the NAD83 datum.

Figure 3 - Reference monument 63-00 as found during the survey

Highlands N.E. Section (QC\ME) – Survey and Inspection

This is one of a series of GPS and conventional survey projects that, when completed, will support further boundary monuments maintenance and produce a high accuracy coordinate definition on the NAD83 datum for this section. For surveying purposes, the section has been broken down into 95 separate traverses, all of which have been surveyed by conventional and/or GPS methods. The goal of this project was to improve the monument position accuracy to up to 1:100,000 (less than 1 cm error in 1 km of measurement) when analyzed; the new observations are much more accurate and well within modern standards. Survey work will continue in this section next field season.

While in the area, the crews also monitored the progress of a nearby vista clearing contract that took place over the summer. In addition, the crews inspected other nearby monuments to determine what maintenance, repair and replacement work will be required in the future.



Figure 4: Doing survey observation with total station.

Highlands S.W. Section (QC\ME) – Vista Clearing and Inspection



69.3 km (43.4 miles) of vista between monuments 405 and 452 were cleared by contract. During the inspection of the work, the IBC inspected 73 monuments. The ongoing efforts over the last years have led to a well-defined open vista from the beginning to the end of this difficult section. Vista clearing work will continue on this section in 2018.

Figure 5 - View of the vista after clearing operations.

West Line (QC/VT) – Monument Maintenance and Inspection

Starting in mid-May a crew of two IBC employees inspected, painted, and where necessary conducted local surveys for the 243 monuments that mark the eastern half of the West Line section of the boundary (Monuments 518 to 631). 84% of these monuments were found to be in fair to good condition. Subsequent to the initial inspection tour, a larger crew retraced their steps with the materials and machines required to repair five existing monuments and install two new monuments that were required to mark the boundary in an area adjacent to a popular snow machine trail.



Figure 7 - Monument 545 after restoration

There are 22 Ports of Entry (POE) along the West Line and lots of human activity on both sides of the boundary in this area. This has resulted in increased requests for local vista clearing and better demarcation of the boundary at specific sites. The IBC expects this increased interest and demand to continue for the foreseeable future.

Lake Superior to Rainy River (ON/MN) – Reference Monument Maintenance



Figure 8 - Repairing RM 518

One crew under one project leader spent the field season inspecting and repairing Reference Monuments in the Lake Superior to Rainy River section. The majority of this section of the boundary must be accessed by boat, or in many areas, by canoe as the boundary passes through 32 lakes and an equal number of connecting rivers, until it reaches the Rainy River. The crews were able to inspect and repair approximately 150 of them in the one field season. In addition, 8 new reference monuments were built to replace out of position monuments and will be surveyed at a later date.



Figure 9 - Restoration of RM 17

Another team inspected and repaired Reference Monuments in this section. The region presents the same logistical challenges as the previous section because it is a water boundary running through the Rainy River and Lake of the Woods. 53 monuments were refurbished.

49th Parallel (AB-SK-MB/MT- ND) – Vista clearing



This has been a traditionally difficult section of the boundary to access for vista clearing. An opportunity arose this year and an IBC crew was diverted from their planned survey project in the area to instead clear what had become mature growth on the vista. Specialized equipment was used to clear the growth and the boundary in this section is now in good condition.

Figure 10 - View of the vista after clearing operations

Southeast Alaska (BC/AK) – Vista Clearing

Also known as the Alaska Panhandle, this is one of the most rugged sections of the boundary. The boundary itself runs along the crest of the Boundary Range of the Cascade Mountains. Bad weather in S.E. Alaska brought this project to a virtual halt. Only 10% of the vista was cleared this year. This project will roll over into 2018 and the clearing will continue.



Figure 11 - View of the vista in Southeast Alaska

141st Meridian (YK\AK) – Survey



This is the last in a series of projects to resurvey the 141st Meridian section of the boundary. The results of these surveys will be analyzed and adjusted to produce a new coordinate definition of the boundary on the modern NAD83 datum.

This particular project extended from the shore of the Arctic Ocean at Monument 0 to Monument 80, 400 km (250 miles) inland. In that distance the boundary covers coastal plains, high plateaus, mountain ranges, permafrost and, this year, several active forest fires. There are few roads in this area and all transportation to the boundary was by helicopter. This precluded any monument maintenance beyond applying a coat of paint to the monuments.

Figure 12 - Helicopter was the workhorse for carrying equipment and personnel

Miscellaneous

In addition to regular maintenance activities, several special requests were dealt with to address specific stakeholders' needs:

North Line (NB/ME) - Monument maintenance

With the objective of improving visibility of the boundary at port of entries, monuments in the vicinity of the Houlton/Woodstock port of entry were inspected and re-furbished. A total of four (4) monuments were cleaned and painted. Upon request of US Border Patrol, a short portion of the vista was cleared of overhanging branches though it had not been too long ago the area had been cut.



Halls Stream (QC|NH) - Inspection

In 2007 and 2008, the IBC launched two prototype projects to monument what were formerly mid-stream Turning Points (TP) defining the international boundary along Halls Stream and the St. Francis River. Many of the mid-stream turning points along Halls Stream are now located on dry land due to the meandering of Halls Stream over the years. While the northern portion of Halls Stream runs over bedrock and its course is relatively stable, the southern portion of Halls Stream runs over alluvial soil and its course can change radically from year-to-year and over the course of decades. In some cases the TPs are now located in the middle of farmers' fields. Without some form of demarcation, the location of the international boundary would be virtually impossible to discern.



This year's monument inspection project was undertaken to document the results of this demarcation 10 years after the monuments were installed. Several of the installed monuments fell victim to further meandering of the stream (see photo above) and others were buried under several feet of gravel and were ineffective in marking the boundary. The Commissioners are currently debating best way to effectively demarcate this type of boundary section.

Clearing of West Line (VT/QC) at Request of DHS

The Department of Homeland Security contacted the IBC to request that a 10.2 mile stretch of the boundary near Stanhope and Ste-Armand Q.C. be cleared. The U.S. section of the IBC let a contract for the completion of the work.

Rebuilding Monument 78 on the 49th Parallel (Manning Park BC)

Monument 78 on the 49th parallel had been reported by a Forestry Department employee as being in poor condition. A crew from the US section rebuilt the monument on its existing base. This monument is at the head of a popular hiking trail and seems to be a popular destination and camping site.



Moving Monument 216C at Kingsgate/ Eastport POE

The supervisor at the POE requested that Monument 216C be moved from its current location to somewhere out of the line of traffic. The crew removed the current monument and created a new base some distance away where there is no traffic but the monument is still highly visible. A new monument will be installed on the base in the near future.



Survey of Hydro Poles in the Fraser River Valley

As part of the IBC's mandate to maintain a clear vista along the Canada/U.S. boundary, we have been in contact with B.C. Hydro since the 1960s regarding a line of hydro poles along 0 Avenue in the Fraser valley. While the poles do not interfere with IBC clearing operations in the area, the poles do increase the cost and complexity of maintaining the boundary in this area. We have a long term understanding with B.C. Hydro that these poles will be moved away from the vista as normal maintenance and upgrade activities take place. This survey was done in support of these efforts and will serve as the basis of further discussions with B.C. Hydro.



COMMISSIONERS ACTIVITIES

Field inspections

The Commissioners conducted one field inspection this year; Commissioner Gagnon and Deputy Commissioners Moore and Fortin visited the Halls Stream section of the boundary. Several difficulties with the current system of marking this section of the boundary were identified. Some monuments had been toppled by the meandering of the stream, others buried under gravel, and even in areas where the monuments remained, it can be difficult to discern the line of the boundary between monuments because the order of the monuments is not clear when standing amongst them.

Given the increasing interest in border related issues and the more frequent questions and concerns being raised by local landowners and other stakeholders, the Commissioners are considering the options for the demarcation of the boundary in these challenging areas.

Commissioners meetings

The Commissioners met twice in 2017, first on April 19 in Washington and again on November 28 in Ottawa. Jean Gagnon attended his first meeting as the Canadian Commissioner following the retirement of Peter Sullivan.

The Commissioners addressed several topics during their meetings:

15 Year Plan

The Commissioners approved a new 15 year plan for the work of the IBC. Within the framework of this new plan, the Commissioners reviewed the work of 2016 and approved a work plan for 2018.

Maintaining an Effective Boundary Line

In line with their mandate, the Commissioners discussed how best to maintain an effective boundary line. In particular, the Halls Stream and Fraser River Valley sections of the boundary have raised issues that the Commission is studying.

Plats and Tables of Geodetic Positions of the boundary

The Commissioners also reviewed the progress of projects to survey and map the boundary on the NAD83 epoch 2010 datum. Two Sections of the boundary have completely updated and approved geographic coordinates and Special Reports and new boundary maps are in final preparation for the Commissioners signature. Several Sections have data that is currently under review and others are at the technical review stage of approval.

All of the data has been stored in the IBC's GIS system and preliminary maps have been created for the entire boundary. As the positional data is collected processed and approved, the GIS will greatly accelerate the production of reports and maps ensuring the IBC can meet the needs of its stakeholders.

REGULATORY ITEMS

The Commission monitors the construction of all works within 10 feet (3 metres) of the boundary. Thus, all construction—whether a ditch, a building, a surface or underground structure (telephone, cable, electrical line or gas pipeline), line of communication, or other—must first be authorized by the Commission. In 2017, the commissioners dealt with the following issues:

1. Replacement of an existing overhead single phase power line by underground three phase power line between Newgate, British Columbia and Lincoln County, Montana;
2. Truss bridge rehabilitation on Chemin de la vallée Missisquoi, Québec, and Glen Sutton Road, Vermont;
3. Installation of buried communication cables along the Quebec/Vermont boundary;
4. Installation of a fiber optic cable across the boundary between Ridgeville, Manitoba and Orleans, Minnesota;
5. Emerson port of entry redevelopment.

PLANNING FOR 2018

The Commissioners have developed a plan for the 2018 season that takes into account the requirements of the 15 year plan and their commitment to the Commissions other initiatives. Under this plan:

The Canadian Section will undertake the following projects:

1. South and Southwest Lines: Vista Clearing by contract
2. Highlands N.E. Section: Monument Maintenance
3. Highlands S.W. Section: Vista Clearing by contract
4. West Line: Vista Clearing (ground treatment only)
5. West Line: Range Mark Preparation (Reconnaissance, Stakeholder consultation, Project Planning)
6. West Line: Boundary Monument Maintenance
7. Lake Ontario and Niagara River: Rebuild a Reference Monument
8. St. Lawrence River: Reference Monument Maintenance (dependent on funding)
9. Halls Stream: Reference Monument Densification Analysis and Construction

The U.S. Section will undertake:

1. North Line (NB/ME) – Vista Clearing; approximately 35 miles from Mon 49 to Mon 117-77
2. Saint John River (NB/ME) – Reference Monument maintenance (cont. from 2017)
3. St. Francis River (NB/ME) – Vista Clearing and maintenance
4. 49th Parallel (MB/MN) – Inspection, maintenance & Survey
5. 49th Parallel (AB-SK-MB/MT-ND) – Inspection, maintenance & Survey
6. 49th Parallel (Pacific to Columbia Valley) - Water boundary Maintenance Contract (Boundary Bay)
7. Southeast Alaska – Vista clearing (4-5 valleys).

ACCOMPLISHMENTS AGAINST THE 15-YEAR PLAN

The IBC conducts its operations within the framework of its 15 Year Plan that can be found in Appendix C. The plan itself represents the knowledge and experience of past Commissioners regarding what types of maintenance each section of the boundary requires and how often each section needs to be revisited in order to meet their mandate of maintaining an effective boundary line. Some sections require attention every three years, others only once every fifteen.

The IBC met the majority of the requirements of the 15 year plan in 2017. Three projects were deferred to a later date; two so that the IBC crews assigned to them could be used to meet an opportunity for vista clearing that arose and the third due to a lack of trained resources. The plans for 2018 are built on the 15 year plan for that year. As with any undertaking of this magnitude, there are variations from the plan. Heavy rain in S.E. Alaska prevented the clearing of the vista in that area in 2017 but the work will continue in 2018. We had planned to do some GPS surveys on the 49th parallel but an opportunity arose for the clearing of the vista in a long neglected nearby section of the boundary so crews were reassigned. This year we received requests to move a monument that was in the path of truck traffic, repair a monument along a well-travelled hiking trail and clear short sections of vista near some Ports of Entry. We responded positively to each of these requests.

In addition to the boundary maintenance work contained in the 15 Year Plan, the IBC has several other related initiatives underway to fulfill the mandates given to the Commissioners. The survey projects undertaken by the IBC are in support of developing a highly accurate digital definition of the boundary on a modern datum that will meet the needs of government agencies, mappers and planners, navigators and the general public. The data will be stored in the IBC's GIS system which will be used to create new maps and data sets showing the boundary. And to an ever larger extent, the IBC web site is being driven from the GIS so that users will have the most recent and up-to-date information available.

REPORT ON COMPARABLE EXPENDITURES

This report shows the total amount spent by both sections of the Commission as at March 31, 2015, for maintenance of the Boundary Line under Section IV of the *Treaty of Washington 1925*.

The cumulative total represents the total spending of each Section, since 1925, on expenditures deemed comparable. Comparable expenditures are the subject of an agreement by both Commissioners as to the interpretation of Section IV of the *Treaty of 1925*, and are revised regularly. The current agreement has been in effect since April 1, 1999. Under the agreement, and according to the Treaty, the expenditures do not include salaries or expenditures by the Commissioner and the Commissioner's assistants, including administrative staff, i.e., the permanent staff of each Section. Therefore, this expenditure report is not a financial report, as it does not include all of the expenditures incurred by each Section.

The purpose of compiling cumulative expenditures since the Commission's origins is to demonstrate that the efforts of both governments are shared equally. Although the cumulative total shows a lag in terms of the expenditures of the U.S. Section, this gap is not a concern, as the U.S. Section's budget currently exceeds the Canadian budget. This is expected to continue, so that the U.S. Section should catch up and close the gap within three or four years.

Given that each country's fiscal year spans two calendar years, the divisible expenditure report does not always reflect all costs associated with current year projects and shows some costs associated with the previous year's projects.

Expenditures are shown in each country's respective currency.

**International Boundary Commission
Joint Annual Report 2017**

Excerpt of Comparable Expenditures to March 31, 2017

	Expended By US Section (USD)	Expended By Canadian Section (CAD)
Total to March 31, 2016	22,629,047.70 \$	24,941,108.08 \$
<u>From April 1, 2016 to March 31, 2017</u>		
Highlands N.E. Section (QC/ME) - Vista Clearing contract from monuments 314 to 405 (125.2 km/77.8 mi)	129,724.00 \$	
Highlands N.E. Section (QC/ME) - Inspection & maintenance from monuments 314 to 405 (125.2 km/77.8 mi)	137,344.02 \$	
West Line (QC/NY) - maintenance from monuments 5 to 26 (27 km/16.8 mi)	122,008.83 \$	
49th Parallel (Columbia Valley to Similkaneen River) (BC/WA) - maintenance from monuments 43 to 73 (78.7 km/48.9 mi)	282,739.10 \$	
Halls Stream (QC/NH) - Survey from monuments TP147 to TP767 (33 km/20.5 mi)	12,871.45 \$	
St. Francis River (QC-NB/ME) - Survey from monuments TP227 to TP374 (32.7 km/20.3 mi)	10,624.19 \$	
49th Parallel – Columbia Valley to Similkameen River (BC/WA) vista clearing contract (37.0 mi / 59.5 km completed remaining 60%) from Mon 72 to Mon 88) IBC 01-15 - 63.4 mi / 102.0 km Mon 72 to Mon 111A	198,790.80 \$	
St. Francis River (ME/QC-NB) - Establish Line Marks from TP 356 to TP 716	102,570.97 \$	
St Croix River (ME/NB) Mon 1 to TP 1089 Reference Monument Recovery	49,361.13 \$	
Lake of the Woods to Lake Superior - Reference Monument Recovery TP 1 to TP 1797	177,565.69 \$	
49th Parallel (MT/BC) - Monument Recovery and Maintenance from Mon 329 to Mon 336	19,621.56 \$	
Southeast AK (AK/BC) - GPS Surveys from Mon 9 to Mon 46	101,338.90 \$	
141st Meridian (AK/YK) - GPS surveys from Mon 139 to Mon 191A	392,974.09 \$	
SE Alaska (AK/BC) - Vista Clearing Contract from Mon 1 to Mon 24 (Zones 1 and 2 completed = 10.3 mi)	107,385.23 \$	
49th Parallel - Lake Osoyoos (MT/BC) - Glacier Park Clearing Zone 5 Mon 273 to Mon 274	25,793.75 \$	
49th Parallel - Lake Osoyoos (MT/BC) - Range Tower Installation	76,160.41 \$	
<u>Other Expenditures</u>		
6x6 ATV (2)	38,710.00 \$	
Trimble GPS Receiver	18,487.50 \$	
Joint Annual Report	1,278.00 \$	
Sub-total for 2016-17	1,251,562.53 \$	753,787.08 \$
Total as of March 31, 2017	23,880,610.23 \$	25,694,895.16 \$

COMMISSIONERS OF THE IBC

UNITED STATES	CANADA
Otto H. Tittmann	1904 – 1915
Edward C. Barnard	1915 – 1921
E. Lester Jones	1921 – 1929
James H. Van Wagenen	1929 – 1935
Thomas Riggs	1935 – 1945
John A. Ulinski	1945 – 1953
Samuel L. Golan	1953 – 1961
Edward J. King	1961 – 1969
Richard L. Herman	1969 – 1977
William M. Schreiber	1977 – 1981
Frank R. Whetstone	1981 – 1985
David C. Fischer	1985 – 1991
Allen C. Kolstad	1991 – 1993
Clyde Moore (Acting)	1993 – 1996
Thomas L. Baldini	1996 – 2002
Dennis L. Schornack	2002 – 2007
David L. Bernhardt	2007 – 2008
Kyle K. Hipsley (Acting)	2008 – 2014
Kyle K. Hipsley	2014 –
William F. King	1904 – 1916
James J. McArthur	1917 – 1924
John D. Craig	1925 – 1931
Noel J. Ogilvie	1931 – 1947
James M. Wardle	1947 – 1950
J. Leslie Rannie	1950 – 1951
J. Earl R. Ross	1951 – 1957
A. Frederick Lambert	1957 – 1976
Alec C. McEwen	1976 – 1991
Suzanne Jacques	1991 – 1996
Michael O'Sullivan	1996 – 2005
Peter J. Sullivan	2005 – 2017
Jean Gagnon	2017 –



OBITUARY

CLYDE R. MOORE

Deputy Commissioner, Retired

1939 - 2018

With deep regrets, the IBC reports that Clyde R. Moore, former Deputy Commissioner, U.S. Section, passed away March 6, 2017 at the age of 79.

Clyde began his career with the IBC on June 14, 1971 and served 30 years with the IBC until his retirement on May 31, 2001. During his career with the IBC he held a number of positions, first as a Field Engineer followed by a long tenure as Deputy Commissioner, and on occasion served as acting Commissioner.

Before moving to the IBC, he worked many years with the USC&GS. He traveled extensively throughout the United States and its possessions while working on triangulation field parties.

During his tenure as Deputy Commissioner, Clyde made a very significant change to the structure of the IBC. He established IBC field offices in Maine, Minnesota and Montana, opening the first field office in Houlton, Maine in 1986. This allowed our field officers to become more familiar with the boundary in their respective areas, which in turn made our field crews more efficient. It also allowed us to enhance our relationships with our stakeholders such as U.S. and Canadian customs agencies, Border Patrol, Royal Canadian Mounted Police as well as local property owners, which all translates into a more "effective" boundary.

Clyde was highly respected not only by his staff and the Canadian section of the IBC, but by his colleagues throughout the surveying community.

After his retirement he continued his relationship with the staff visiting the office frequently throughout the years. The IBC continued to benefit from his knowledge of the boundary by contracting him to work on a number of small projects. He was always willing to share his knowledge with the entire staff.

It's impossible to write in a few paragraphs what Clyde meant to the IBC. He created an atmosphere of family within the staff and led by example, with hard work and dedication, expecting the same from all of us. I believe the following quote best describes Mr. Moore:

"If your actions inspire others to dream more, learn more, do more, and become more, you are a leader."
-- John Quincy Adams

Deputy Commissioner, "Clyde" R. Moore will be missed and will forever be in our thoughts.

CERTIFICATION

We certify that the foregoing is a true record of the work done by the Commissioners during the year ending December 31, 2017 on the maintenance of the International Boundary Line between Canada and the United States of America, and that the plats and tables submitted herein show the true location and geodetic position of all monuments moved and all additional monuments and marks established within the year, in accordance with the provisions of Article IV of the Treaty between the United States of America and His Britannic Majesty in respect of Canada signed at Washington, February 24, 1925.

Jean Gagnon
Commissioner for Canada

Kyle K. Hipsley
Commissioner for the United States



**International Boundary Commission
Joint Annual Report 2017**

APPENDIX A – DETAILS OF MAINTENANCE AND SURVEY WORK

**International Boundary Commission
Joint Annual Report 2017**

**International Boundary Commission
Joint Annual Report 2017**

Legend

Boundary Monument Type:	MON	Monument (Artificial feature set to mark the international boundary)
	LM	Line Mark (Artificial feature set between established boundary points)
	RG	Range Mark (Artificial feature set to define turning points by mean of alignment)
	RM	Reference Monument (Artificial feature set to define turning points by traverse)
Reconnaissance:	G	Recovered In Good Condition
	F	Recovered in Fair Condition (requires minor repair)
	P	Recovered in Poor Condition (requires major repair)
	D	Destroyed (evidence found but Monument not in place)
	NR	Not Recovered (no evidence found or inadequate search)
Established:	NM	New Monument constructed (in new location)
	R	Renewed (in same location)
Repairs:	MI	Minor repairs to base (cracks patched, plumbed, dirt packed at base, etc)
	MA	Major repairs (new marker installed, base partially replaced or recapped)
Painted:	MP	Monument Painted
Description:	DU	Description Updated
	ND	New Description (newly established monuments only)
Photo:	YES	Photographed
	NO	Not Photographed
Monument Surveyed:	S	Survey performed to position the monument

***Passamaquoddy Bay
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RG M 1	G					NO	
RG M 2	G					NO	
RG M 4	G					NO	
RG M 3	G					NO	
RG M 5	G					NO	
RG M 6	G					NO	
RG M 11	G					NO	
RG M 18	G					NO	
RG M 9	G					NO	
RG M 10	G					NO	
RG M 7	G					NO	
RG M 17	G					NO	
RG M 13	G					NO	
RG M 14	G					NO	
RG M 8	G					NO	
RG M 15	G					NO	
RG M 12	G					NO	
RG M 16	G					NO	
RG M 30	G					NO	
RG M 19	G					NO	

**International Boundary Commission
Joint Annual Report 2017**

***Passamaquoddy Bay
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RG M 20	G					NO	
RG M 29	G					NO	
RG M 22	G					NO	
RG M 21	G					NO	
RG M 32	G					NO	
RG M 31	G					NO	
RG M 24	G					NO	
RG M 23	G					NO	
RG M 25	G					NO	
RG M 26	G					NO	
RG M 28	G					NO	
RG M 27	G					NO	
RG M 36	G					NO	
RG M 33	G					NO	
RG M 34	G					NO	
RG M 34	G					NO	
RG M 35	G					NO	
RG M 37	G					NO	
RG M 38	G					NO	
RG M 46	G					NO	
RG M 40	G					NO	
RG M 39=GUNNER	G					NO	
RG M 45	G					NO	
RG M 44	G					NO	
RG M 43	G					NO	
RG M 41	G					NO	
RG M 42	G					NO	
RG M 48	G					NO	
RG M 47	G					NO	

***North Line
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 19A1	G			MP		YES	
MON 19A2	G			MP		YES	
MON 19A3	G			MP		YES	
MON 19A4	G			MP		YES	

International Boundary Commission
Joint Annual Report 2017

Saint John River
(New Brunswick/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM S-18-40	D					NO	
RM S-23A	D					NO	
RM S-23-52	D					NO	
RM S-25-52	D					NO	
RM S-26-52	D					NO	
RM S-29-52	D					NO	
RM S-31-52	D					NO	
RM C70-75	G			MP		YES	
RM C70A-76	G			MP		YES	
RM S-70-51	D					NO	
RM 141-51	D					NO	
RM 142-51	D					NO	
RM S2A-72	G			MP		YES	
RM S2	G			MP		YES	
RM S3	P					YES	
RM S4-72	D					NO	
RM S-4A	D					NO	
RM S4	P					YES	
RM S5	D					NO	
RM S-5-72	G			MP		YES	
SITE RM S6	D					NO	
RM S-6A-72	D					NO	
SITE RM S7	D					NO	
RM S-7-52	D					NO	
RM S7-72	NR					NO	
RM S-8-52	P					YES	
RM S8B-72	G			MP		YES	
RM S-8A	D					NO	
RM S-9A	D					NO	
SITE RM S9	G			MP		YES	
RM S-10-52	D					YES	
SITE RM S10	D					NO	
RM S11-72	G					YES	
RM S11	P					YES	
SITE RM S12	D					NO	
RM S12-72	G			MP		YES	
RM S13-72	G			MP		YES	
RM S-13-31	D					NO	
SITE RM S13	D					NO	
RM S14	D					NO	
RM S-14-57	G			MP		YES	
RM S15-72	G			MP		YES	
RM C14	D					NO	
RM S-15-52	D					NO	
SITE RM S15	D					NO	

**International Boundary Commission
Joint Annual Report 2017**

***Saint John River
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM C15	G			MP		YES	
SITE RM S16	D					NO	
RM S16-40	P					YES	
SITE RM C16	D					NO	
RM S17	F			MP		YES	
RM S18-72	G			MP		YES	
RM C-17A	P					YES	
SITE RM S18	D					NO	
RM C18-72	G			MP		YES	
RM S19-52	D					NO	
SITE RM S19	D					NO	
SITE RM C18	D					NO	
RM S20-72	G			MP		YES	
RM C18A-72	D					NO	
RM C19-72	D					NO	
RM C-19-52	D					NO	
SITE RM C19	D					NO	
RM S20	D					NO	
RM C20-72	D					NO	
SITE RM C20	D					NO	
RM S21	P					YES	
RM C21-72	P					YES	
RM S22	D					NO	
SITE RM C21	D					NO	
RM S23A-59	G			MP		YES	
RM S23A-59	D					NO	
SITE RM S23	D					NO	
RM C23-72	D					YES	
RM C-23-52	D					NO	
RM S24A-72	G			MP		YES	
SITE RM C23	D					NO	
RM S24	G			MP		YES	
RM S25-73	NR					NO	
SITE RM S25	D					NO	
RM S26-73	G			MP		YES	
SITE RM S26	D					NO	
RM C25-52	D					YES	
RM S27-52	D					NO	
RM S27	P					YES	
SITE RM C25	D					NO	
RM C26-73	D					NO	
RM C-26-52	D					NO	
SITE RM C26	D					NO	
RM S28	D					NO	
RM C-27-54	D					NO	

International Boundary Commission
Joint Annual Report 2017

Saint John River
(New Brunswick/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
SITE RM C27	D					NO	
RM C27-73	G			MP		YES	
RM S29A-52	G			MP		YES	
RM S29	D					NO	
RM S30-52	P					YES	
SITE RM S30	D					NO	
RM C29-52	D					NO	
RM S31-73	D					YES	
SITE RM S31	D					NO	
RM C31-73	G			MP		YES	
RM C-31-52	D					NO	
SITE RM C31	D					NO	
RM C32	D					NO	
SITE RM C33	D					NO	
RM C-33-40	G			MP		YES	
RM C33-73	D					NO	
RM C34	NR					NO	
RM C-35-52	D					NO	
RM C35-73	G			MP		YES	
SITE RM C35	D					NO	
SITE RM C36	D					NO	
RM C-36-52	P			MP		YES	
RM C36-75	G			MP		YES	
RM C37-73	G			MP		YES	
SITE RM C37	D					NO	
RM C-37-51	D					NO	
SITE RM C38	D					NO	
RM C-38-51	G			MP		YES	
RM C-39A-73	NR					NO	
RM C39A-75	G			MP		YES	
RM C39	D					YES	
RM C40-75	G			MP		YES	
SITE RM C41	D					NO	
RM C41-51	D					YES	
RM C42-75	G			MP		YES	
SITE RM C42	D					NO	
RM C-42-52	D					NO	
RM C43-75	G			MP		YES	
SITE RM C43	D					NO	
RM S-46A	F			MP		YES	
SITE RM S46	D					NO	
RM S46-75	G			MP		YES	
RM C44A-75	G			MP		YES	
RM C44	P					YES	
RM C44B-75	D					YES	

**International Boundary Commission
Joint Annual Report 2017**

***Saint John River
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM C-45-52	D					NO	
SITE RM C45	D					NO	
RM C45A-75	G			MP		YES	
RM S47	P					YES	
RM S-47-51	G			MP		YES	
RM S48	G			MP		YES	
RM C46	NR					NO	
SITE RM S49	D					NO	
RM S49-54	G			MP		YES	
RM C47	P					YES	
RM C48A-75	G					YES	
RM C48	G					YES	
RM S50-54	G			MP		YES	
SITE RM S50	D					NO	
RM C49-75	G					YES	
RM C49	P					YES	
RM S-51-51	D					NO	
RM C49A-75	G					YES	
RM S52-51	G			MP		YES	
SITE RM S52	D					YES	
RM C-50A-75	D					NO	
RM C51-75	D					NO	
RM C-51-51	D					NO	
RM C51	D					NO	
RM S53	D					NO	
RM S-53A	D					NO	
RM S53-73	G			MP		YES	
RM C52	P					YES	
RM S54-57	D					NO	
RM S54	P					YES	
RM C52A-73	NR					NO	
RM S54A-75	NR					NO	
RM C53	P					YES	
SITE RM S55	D					NO	
RM S-55-51	D					NO	
RM S55-73	G			MP		YES	
RM C54A-75	G					YES	
RM C54	P		MA			NO	
SITE RM S56	P					YES	
RM S56-75	G			MP		YES	
RM S57-73	G			MP		YES	
RM C55-75	G			MP		YES	
RM C-55-51	D					NO	
RM C55A-51	D					NO	
SITE RM C55	D					NO	

International Boundary Commission
Joint Annual Report 2017

Saint John River
(New Brunswick/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM S-57-51	D					NO	
SITE RM S57	D					NO	
RM S58-75	D					NO	
RM C-56-51	D					NO	
RM C56	D					NO	
SITE RM S58	D					NO	
RM S-58-40	D					NO	
RM C56A-75	G					YES	
SITE RM S59	D					NO	
RM S-59-51	D					NO	
RM C-57-51	D					NO	
SITE RM C57	D					NO	
RM S60	P		MA	MP		YES	
RM C58	D					NO	
RM C57-75	D					NO	
RM S60-75	G			MP		YES	
RM C-58-52	D					NO	
RM C59A-51	D					NO	
RM C59-75	D					NO	
SITE RM C59	P					YES	
RM S61	D					NO	
RM S62-51	D					NO	
SITE RM S62	D					NO	
SITE RM C60	D					NO	
RM C60-75	G			MP		YES	
RM S-63-51	D					NO	
RM S-63A	D					NO	
RM S63-75	G			MP		YES	
RM C61A-75	G			MP		YES	
SITE RM C61	D					NO	
RM C62-75	G			MP		YES	
RM S64-75	G			MP		YES	
RM S-65-51	D					NO	
RM S65-75	D					NO	
SITE RM C63	D					NO	
RM C-63-51	D					NO	
SITE RM S65	D					NO	
RM C63-75	NR					NO	
SITE RM C64	P					YES	
SITE RM C65	D					NO	
RM C64-76	NR					NO	
RM S-66-51	D					NO	
SITE RM S66	D					NO	
RM S66-76	D					NO	
RM C65-75	NR					NO	

**International Boundary Commission
Joint Annual Report 2017**

***Saint John River
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM C-65-51	D					NO	
RM S67-76	NR					NO	
RM S-67-51	D					NO	
SITE RM S67	D					NO	
RM C65A-76	NR					NO	
RM C66	D					YES	
RM C66A-75	G			MP		YES	
RM S-68-51	D					NO	
RM S-68-75	G			MP		YES	
RM 139-76	G			MP		YES	
SITE RM 139	P					YES	
SITE RM S70	D					NO	
RM 140	G			MP		YES	
RM 142-76	G			MP		YES	
RM S70-75	G			MP		YES	
RM S71A-51	G			MP		YES	
SITE RM S71	D					NO	
RM C67	F			MP		YES	
RM S72A-75	G			MP		YES	
RM S72-54	G					NO	
SITE RM S72	D					NO	
RM C68	P					YES	
RM C68A-75	NR					NO	
RM C68B-76	G			MP		YES	
SITE RM S73	F			MP		YES	
RM S73A-76	NR					NO	
RM S73-75	D					NO	
SITE RM C69	P		MA	MP		YES	
RM C69A-75	G			MP		YES	
RM S74A-51	NR					NO	
RM S-74-51	NR					NO	
SITE RM S74	D					NO	
SITE RM C70	P		MA	MP		YES	
RM C-71-31	D					NO	
RM 147-77	G			MP		YES	
SITE RM C71	D					NO	
RM C71-76	G			MP		YES	
RM S75A-76	G			MP		YES	
RM S75	F			MP		YES	
SITE RM S69	G			MP		YES	
RM S69A-76	G					YES	
RM S76-31	G			MP		YES	
SITE RM S76	D					NO	
RM 149	G			MP		YES	
RM C72A-76	G					YES	S

**International Boundary Commission
Joint Annual Report 2017**

***Saint John River
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
SITE RM C72	P		MA	MP		YES	
RM 151	D					NO	
RM 151A-76	D					NO	
SITE RM 151A	D					NO	
RM S77	F			MP		YES	
RM 153	G			MP		YES	
RM S78-76	F			MP		YES	
RM S-78-53	D					NO	
SITE RM S78	D					NO	
RM C73	P		MA	MP		YES	
RM S-79-53	D					NO	
RM S79	D					NO	
RM S79-76	G			MP		YES	
RM C74	D					NO	
SITE RM S80	D					NO	
RM S80-76	G			MP		YES	
RM C75	P		MA	MP		YES	S
RM S81-76	D					NO	
RM S81A-54	G			MP		YES	
SITE RM S81	D					YES	
RM C76A-51	G			MP		YES	
RM C-76-52	P		MA	MP		YES	S
SITE RM C76	P		MA	MP		YES	S
SITE RM S82	P		MA	MP		YES	
RM S82A-76	G			MP		YES	
RM C77	F			MP		YES	S
SITE RM S83	D					NO	
RM S83-51	F					YES	
SITE RM S84	D					NO	
RM S-84-54	D					NO	
RM S84A-76	NR					NO	
RM C78A-76	G			MP		YES	
SITE RM C78	P		MA	MP		YES	S
SITE RM S85	D					NO	
RM C79	F			MP		YES	S
RM C79A-76	G			MP		YES	S
RM S85-76	G			MP		YES	
SITE RM S86	D					YES	
RM S86-76	D					NO	
SITE RM C80	P		MA	MP		YES	S
RM C80-76	G			MP		YES	S
SITE RM C81	P		MA	MP		YES	S
RM C-81-52	P		MA	MP		YES	S
RM C81A-76	G			MP		YES	S
SITE RM S87	G			MP		YES	

**International Boundary Commission
Joint Annual Report 2017**

***Saint John River
(New Brunswick/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM S87-76	NR					NO	
RM S88	F			MP		YES	S
SITE RM S89	P		MA	MP		YES	S
RM S89A-76	G			MP		YES	
SITE RM C82	D					NO	
RM C82-76	D					NO	
RM C83-76	D					NO	
SITE RM S90	D					NO	
RM S90-76	G			MP		YES	S
RM C-83-51	D					NO	
SITE RM C83	D					NO	
RM S91-76	G			MP		YES	
RM C84-76	NR					NO	
SITE RM S91	P		MA	MP		YES	S
RM C-84-51	D					NO	
SITE RM C84	D					NO	
RM S92-76	G			MP		YES	S
RM C-85-51	D					NO	
RM C85	D					NO	
SITE RM S92	D					NO	
RM S-93-51	D					NO	
RM C-86-76	G			MP		YES	S
SITE RM S93	D					NO	
RM C86	D					NO	
RM S93-76	G			MP		YES	
RM S94-76	D					NO	
SITE RM S94	D					NO	
SITE RM C87	P		MA	MP		YES	S
RM C87-76	G			MP		YES	S
RM S95	G			MP		YES	
RM 154	G			MP		YES	
RM S-95-76	G			MP		YES	
RM C88-52	P		MA	MP		YES	S
SITE RM C88	P		MA	MP		YES	S
RM 155	G			MP		YES	
RM S-96-52	D					NO	
RM S96-76	G			MP		YES	
SITE RM S96	D					NO	
RM C89	F			MP		YES	S
RM C90-76	NR					NO	
RM S96A-77	G					YES	
SITE RM C90	P		MA	MP		YES	S
RM C91-77	NR					NO	
RM S97	F			MP		YES	
SITE RM C91	P		MA	MP		YES	S

International Boundary Commission
Joint Annual Report 2017

Saint John River
(New Brunswick/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM S98-77	G			MP		YES	
SITE RM S98-51	D					NO	
SITE RM S98	D					NO	
RM 156	G			MP		YES	
SITE RM C92	D					NO	
RM C92-77	G			MP		YES	S
RM 157	D					YES	
RM 158-77	G			MP		YES	
RM C-92A	D					NO	
SITE RM S99	D					NO	
RM S99-77	G			MP		YES	
SITE RM C93	P		MA	MP		YES	S
RM 159A-77	G					YES	
RM 159B	P					YES	
RM C93-77	G			MP		YES	
RM 159-77	D					NO	
RM 160-77	G			MP		YES	
RM 162-77	D					NO	
RM C94A-77	G			MP		YES	
RM 161-77	G			MP		YES	
SITE RM C94	G			MP		YES	S
RM 163-77	G			MP		YES	
RM S100-77	G			MP		YES	
SITE RM S100	D					NO	
RM C94B-77	G			MP		YES	
SITE RM S101	G			MP		YES	
RM S101A-77	G			MP		YES	
RM C95A-77	G			MP		YES	
SITE RM C95	G			MP		YES	
RM S102	G			MP		YES	
SITE RM C96	D					NO	
RM 163A-77	NR					NO	
RM C96-77	G			MP		YES	
RM S103-51	G			MP		YES	
RM C-97-51	D					NO	
SITE RM C97	D					NO	
SITE RM S103	D					NO	
RM C97-77	D					NO	
RM 164	G			MP		YES	
RM S104-77	G			MP		YES	S
SITE RM S104	D					NO	
RM C98-77	G					YES	
SITE RM C98	P		MA	MP		YES	S
RM 165-77	D					NO	
RM 166-77	D					YES	

International Boundary Commission
Joint Annual Report 2017

Saint John River
(New Brunswick/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 167-77	D					YES	
SITE RM 168	G			MP		YES	
RM 168A-77	G			MP		YES	
RM S105-77	G			MP		YES	
SITE RM S105	P		MA	MP		YES	S
RM C99	F			MP		YES	S
RM 169	P			MP		YES	
RM C100-51	G			MP		YES	S
SITE RM C100	D					NO	
RM S106-77	G			MP		YES	
RM S-106-52	D					NO	
SITE RM S106	D					NO	
RM S107A-77	G			MP		YES	S
SITE RM S107	G			MP		YES	
RM C101	P		MA	MP		YES	S
RM C102	G			MP		YES	
RM S-108-52	D					NO	
RM S108-77	G			MP		YES	
RM C102-77	G			MP		YES	S
SITE RM S109	G			MP		YES	
RM S109A-77	G					YES	
SITE RM C103	D					NO	
RM C103-77	G			MP		YES	S
RM C104-77	G			MP		YES	S
SITE RM C104	P		MA	MP		YES	S
RM S110-77	G			MP		YES	
SITE RM S110	G			MP		YES	
RM S-111	G			MP		YES	S
RM S111-77	NR					NO	
RM C-105	P		MA	MP		YES	S
RM C105-77	G			MP		YES	S
RM S112-77	G			MP		YES	S
RM S-112	P		MA	MP		YES	S
RM 171-77	G			MP		YES	
SITE RM C106	D					NO	
RM C-106-77	D					NO	
RM 172-77	G			MP		YES	
RM S-90A	D					NO	
RM S-87-51	D					NO	
RM C22	P					YES	
RM 170-77	P					YES	
RM S-90-51	D					NO	

International Boundary Commission
Joint Annual Report 2017

St. Francis River
(New Brunswick/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 173-77	NR					NO	
RM S113-77	G			MP		YES	S
RM S-113	P		MA	MP		YES	S
RM C109	P		MA	MP		YES	S

Southwest Branch of the St. John River
(New Brunswick, Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM C62-00	G					YES	S
RM C63-00	G					YES	S
RM C64	G					YES	S
RM C65	G					YES	S
RM C68	P					YES	S
RM C69	F					YES	S
RM C70	G					YES	S
RM C75	G					YES	S
RM S73	G					YES	S

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 318.8	G					NO	S
MON 318A	P					NO	S
MON 319.21	F					NO	S
MON 319.22	F					NO	S
MON 320.13	G					NO	S
MON 320.16	G					NO	S
MON 321.4	G					NO	S
MON 321.5	G					NO	S
MON 322.3	G					NO	S
MON 322.4	G					NO	S
MON 323.4	G					NO	S
MON 323.5	G					NO	S
MON 324.7	F					NO	S
MON 324.8	G					NO	S
MON 329.29	G					YES	
MON 329.30	G					YES	

**International Boundary Commission
Joint Annual Report 2017**

***Highlands N.E. Section
(Quebec/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 329.31	G					YES	
MON 329.32	G					YES	
MON 329.33	G					YES	
MON 331.15	G					YES	
MON 340.27	G					YES	
MON 346.1	P					NO	S
MON 346.2	G					NO	S
MON 346.3	G					NO	S
MON 346.4	G					NO	S
MON 346.5	F					NO	S
MON 346.6	G					NO	S
MON 346.7	P					NO	S
MON 346.8	G					NO	S
MON 346.9	G					NO	S
MON 346.10	F					NO	S
MON 346.11	P					NO	S
MON 346.12	P					NO	S
MON 346.12A	F	R				YES	S
MON 346.13	G					NO	S
MON 346.14	P					NO	S
MON 346.15	G					NO	S
MON 346.16	F					NO	S
MON 346.17	P					NO	S
MON 347	D					NO	S
MON 347.1	P					NO	S
MON 347.2	G					NO	S
MON 347.3	G					NO	S
MON 347.4	G					NO	S
MON 347.5	D					NO	S
MON 347.6	P					NO	S
MON 347.7	G					NO	S
MON 347.8	G					NO	S
MON 347.9	P					NO	S
MON 347.10	P					NO	S
MON 347.11	G					NO	S
MON 347.12	G					NO	S
MON 347.13	F					NO	S
MON 347.14	G					NO	S
MON 347.15	G					NO	S
MON 347.16	P					NO	S
MON 347.17	P					NO	S
MON 347.18	G					NO	S
MON 347.19	P					NO	S
MON 347.20	G					NO	S
MON 347.21	G					NO	S

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 347.22	G					NO	S
MON 347.23	G					NO	S
MON 347.24	P					NO	S
MON 347.25	P					NO	S
MON 347.26	D					NO	S
MON 347.27	P					NO	S
MON 347.28	G					NO	S
MON 347.29	F					NO	S
MON 347.30	G					NO	S
MON 347.31	G					NO	S
MON 347.32	F					NO	S
MON 347.33	F					NO	S
MON 347.34	G					NO	S
MON 348	G					NO	S
MON 348.1	G					NO	S
MON 348.2	G					NO	S
MON 348.3	P					NO	S
MON 348.4	G					NO	S
MON 348.5	G					NO	S
MON 348.6	G					NO	S
MON 348.7	P					NO	S
MON 348.8	F					NO	S
MON 348.9	G					NO	S
MON 348.10	P					NO	S
MON 348.11	F					NO	S
MON 348.12	G					NO	S
MON 348.13	F					NO	S
MON 348.14	G					NO	S
MON 348.15	P					NO	S
MON 348.16	G					NO	S
MON 348.17	P					NO	S
MON 348.18	P					NO	S
MON 348.19	P					NO	S
MON 348.20	G					NO	S
MON 348.21	G					NO	S
MON 348.22	G					NO	S
MON 348.23	G					NO	S
MON 348.24	G					NO	S
MON 348.25	G					NO	S
MON 348.26	P					NO	S
MON 348.27	P					NO	S
MON 348.28	D					NO	S
MON 348.29	P					NO	S
MON 348.30	F					NO	S
MON 348.31	G					NO	S

International Boundary Commission
Joint Annual Report 2017

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 348.32	F					NO	S
MON 348.33	F					NO	S
MON 348.34	G					NO	S
MON 348.35	F					NO	S
MON 348.36	G					NO	S
MON 348.37	G					NO	S
MON 348.38	G					NO	S
MON 349	G					NO	S
MON 349.1	G					NO	S
MON 349.2	G					NO	S
MON 349.3	P					NO	S
MON 349.4	G					NO	S
MON 349.5	G					NO	S
MON 349.6	F					NO	S
MON 349.7	G					NO	S
MON 349.8	G					NO	S
MON 351B	P					NO	
MON 352	G					NO	
MON 353	G	R		MP		YES	
MON 356.5	G					NO	S
MON 356.6	G					NO	S
MON 367.2	G					YES	
MON 367.3	G	R				YES	
MON 367.4	P	R				YES	
MON 367.5	G					YES	
MON 367.6	G					YES	
MON 367.7	G					YES	
MON 367.8	G					YES	
MON 367.9	G					YES	
MON 367.10	G					YES	
MON 367.11	G					YES	
MON 367.12	P					YES	
MON 367.13	G					YES	
MON 367.14	P	R				YES	
MON 367.15	G					YES	
MON 367.16	G					YES	
MON 368	F	R				YES	
MON 368.1	G					YES	
MON 368.2	P					YES	
MON 368.3	D					YES	
MON 368.4	P					YES	
MON 368.5	F					YES	
MON 368.6	G					YES	
MON 368.7	G					YES	
MON 368.8	P					YES	

International Boundary Commission
Joint Annual Report 2017

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 368.9	G	R				YES	
MON 368.10	P					YES	
MON 368.11	G					YES	
MON 368.12	G	R				YES	
MON 368.13	G					YES	
MON 368.14	P					YES	
MON 368.15	G					YES	
MON 368.16	F					YES	
MON 368.17	G					YES	
MON 368.18	G					YES	
MON 368.19	G					YES	
MON 368.20	G					YES	
MON 368.21	G					YES	
MON 368.22	G					YES	
MON 368.23	G					YES	
MON 368.24	P					YES	
MON 369	G	R				YES	S
MON 369.1	F					YES	S
MON 369.2	G					YES	S
MON 369.3	G					YES	S
MON 369.4	G					YES	S
MON 369.5	F					YES	S
MON 369.6	F					YES	S
MON 369.7	G					YES	S
MON 369.8	G					YES	S
MON 369.9	G					YES	S
MON 369.10	G					YES	S
MON 369.11	F					YES	S
MON 369.12	G					YES	S
MON 369.13	G					YES	S
MON 369.14	G					YES	S
MON 369.15	F					YES	S
MON 370	G	R				YES	S
MON 370.1	G					YES	S
MON 370.2	G					YES	S
MON 370.3	F					YES	S
MON 370.4	F					YES	S
MON 370.5	F					YES	S
MON 370.6	P					YES	S
MON 370.7	F	R				YES	S
MON 370.8	P					YES	S
MON 370.9	G					YES	S
MON 370.10	G					YES	S
MON 371	F	R				YES	S
MON 371.1	G					YES	S

International Boundary Commission
Joint Annual Report 2017

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 371.2	G					YES	S
MON 371.3	G					YES	S
MON 371.4	G					YES	S
MON 371.5	G					YES	S
MON 371.6	G					YES	S
MON 371.7	G					YES	S
MON 371.8	G					YES	S
MON 371.9	F					YES	S
MON 371.10	G					YES	S
MON 371.11	G					YES	S
MON 371.12	G					YES	S
MON 371.13	G					YES	S
MON 371.14	P					YES	S
MON 371.15	G					YES	S
MON 371.16	G					YES	S
MON 371.17	G					YES	S
MON 372	G	R				YES	S
MON 372.1	G					YES	S
MON 372.2	G					YES	S
MON 372.3	G					YES	S
MON 373	G					NO	S
MON 373.1	G					NO	S
MON 373.2	G					NO	S
MON 373.3	G					NO	S
MON 373.4	P					NO	S
MON 373.5	P					NO	S
MON 373.6	P					NO	S
MON 373.7	P					NO	S
MON 374	G	R				YES	S
MON 374.1	G	R				YES	S
MON 374.2	G	R				YES	S
MON 374.3	G					YES	S
MON 374.4	G					YES	S
MON 374.5	G	R				YES	S
MON 374.6	G	R				YES	S
MON 374.7	G					YES	S
MON 374.8	G	R				YES	S
MON 374.9	F					YES	S
MON 374.10	G					YES	S
MON 374.11	G					YES	S
MON 374.12	G					YES	S
MON 374.13	F					YES	S
MON 374.14	G					YES	S
MON 374.15	G					YES	S
MON 374.16	G					YES	S

**International Boundary Commission
Joint Annual Report 2017**

***Highlands N.E. Section
(Quebec/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 374.17	G					YES	S
MON 374.18	G					YES	S
MON 374.19	G					YES	S
MON 374.20	F					YES	S
MON 374.21	F					YES	S
MON 374.22	F					YES	S
MON 374.23	G					YES	S
MON 374.24	G					YES	S
MON 374.25	G					YES	S
MON 374.26	F					YES	S
MON 374.27	G					YES	S
MON 375	D					YES	S
MON 375.1	G					YES	S
MON 375.2	F					YES	S
MON 375.3	G					YES	S
MON 375.4	G					YES	S
MON 375.5	P					YES	S
MON 375.6	G					YES	S
MON 375.7	G					YES	S
MON 375.8	G					YES	S
MON 375.9	F					YES	S
MON 375.10	G					YES	S
MON 376	G	R				YES	S
MON 376.1	F					YES	S
MON 376.2	G					YES	S
MON 376.3	G					YES	S
MON 376.4	G					YES	S
MON 376.5	G					YES	S
MON 376.6	G					YES	S
MON 376.7	F					YES	S
MON 376.8	G					YES	S
MON 377	G	R				YES	
MON 377.1	G					YES	
MON 377.2	F					YES	
MON 377.3	G					YES	
MON 377.4	G					YES	
MON 377.5	G					YES	
MON 378	G					YES	
MON 378.1	G					YES	
MON 378.2	G					YES	
MON 378.3	G					YES	
MON 378.4	G					YES	
MON 378.5	G					YES	
MON 378.6	G					YES	
MON 378.7	F					YES	

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 378.8	G					YES	
MON 378.9	G					YES	
MON 378.10	F					YES	
MON 378.11	G					YES	
MON 378.12	G					YES	
MON 378.13	G					YES	
MON 378.14	G					YES	
MON 378.15	P					YES	
MON 378.16	F					YES	
MON 378.17	F					YES	
MON 378.18	G					YES	
MON 378.19	F					YES	
MON 378.20	G					YES	
MON 378.21	G					YES	
MON 378.22	G					YES	
MON 378.23	G					YES	
MON 378.24	G					YES	
MON 378.25	P					YES	
MON 379	G	R				YES	
MON 379.1	G					YES	
MON 379.2	G					YES	
MON 379.3	G					YES	
MON 379.4	G	R				YES	
MON 379.5	G					YES	
MON 379.6	G					YES	
MON 379.7	G					YES	
MON 379.8	G					YES	
MON 380	G	R				YES	
MON 380.1	G					YES	
MON 380.2	G	R				YES	
MON 380.3	G					YES	
MON 380.4	P					YES	
MON 380.5	G					YES	
MON 380.6	G					YES	
MON 380.7	G					YES	
MON 380.8	G	R				YES	
MON 380.9	G	R				YES	
MON 380.10	G					YES	S
MON 380.11	G	R				YES	
MON 380.12	G					YES	S
MON 380.13	G					YES	
MON 380.14	G					YES	
MON 380.15	G					YES	
MON 380.16	G					YES	
MON 380.17	G					YES	

**International Boundary Commission
Joint Annual Report 2017**

***Highlands N.E. Section
(Quebec/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 380.18	G					YES	
MON 380.19	G					YES	
MON 380.20	G					YES	
MON 380.21	G	R				YES	
MON 380.22	G					YES	
MON 380.23	G					YES	
MON 381	G					YES	
MON 381.1	G					YES	
MON 381.2	G					YES	
MON 381.3	G					YES	
MON 381.4	G					YES	
MON 381.5	G					YES	
MON 381.6	G					YES	
MON 381.7	G					YES	
MON 381.8	G					YES	
MON 381.9	G					YES	
MON 381.10	G	R				YES	
MON 381.11	G					YES	
MON 381.12	G					YES	
MON 381.13	G					YES	
MON 381.14	G					YES	
MON 381.15	G					YES	
MON 382.8	F					NO	S
MON 382.9	G					NO	S
MON 382.14	G					YES	
MON 382.15	G	R				YES	
MON 382.16	G					YES	
MON 382.17	G					YES	
MON 383	P	R				YES	
MON 383.1	G					YES	
MON 383.2	G					YES	
MON 383.3	G					YES	
MON 383.4	G					YES	
MON 383.5	G					YES	
MON 383.6	G					YES	
MON 383.7	G					YES	
MON 383.8	G					YES	
MON 383.9	G					YES	
MON 383.10	G					YES	
MON 383.11	G					YES	
MON 383.12	G					YES	
MON 383.13	G	R				YES	
MON 383.14	G					YES	
MON 383.15	G					YES	
MON 383.16	G					YES	

**International Boundary Commission
Joint Annual Report 2017**

***Highlands N.E. Section
(Quebec/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 383.17	G	R				YES	
MON 383.18	G					YES	
MON 383.19	G					YES	
MON 383.20	G					YES	
MON 383.21	G					YES	
MON 383.22	G					YES	
MON 383.23	G					YES	
MON 383.24	G					YES	
MON 383.25	G					YES	
MON 383.26	G					YES	
MON 383.29	G					NO	S
MON 383.30	G					YES	S
MON 383.31	G					YES	
MON 383.32	G					YES	
MON 383.33	F					YES	
MON 383.34	G					YES	
MON 383.35	F					YES	
MON 383.36	G					YES	
MON 383.37	G					YES	
MON 383.38	G					YES	
MON 383.39	G					YES	
MON 383.40	F					YES	
MON 383.41	F					YES	
MON 383.42	G					YES	
MON 384	P					YES	
MON 384.1	G					YES	
MON 384.2	G					YES	
MON 384.3	G					YES	
MON 384.4	G					YES	
MON 384.5	G					YES	
MON 384.6	G					YES	
MON 384.7	G					YES	
MON 384.8	G					YES	
MON 385	P					YES	
MON 385.1	G					YES	
MON 385.2	G					YES	
MON 385.3	G					YES	
MON 385.4	G	R				YES	
MON 385.5	G					YES	
MON 385.6	G					YES	
MON 385.7	G					YES	
MON 385.8	G					YES	
MON 385.9	F					YES	
MON 385.10	F					YES	
MON 385.11	G					YES	

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 385.12	G					YES	
MON 385.13	G					YES	
MON 385.14	G					YES	
MON 385.15	G					YES	
MON 385.16	G					YES	
MON 385.17	G	R				YES	
MON 385.18	G					YES	
MON 385.19	G					YES	
MON 385.20	G					YES	
MON 385.21	G					YES	
MON 385.22	G					YES	
MON 385.23	G					YES	
MON 385.24	G					YES	S
MON 385.25	G					YES	S
MON 385.26	G					YES	S
MON 385.27	G					YES	S
MON 385.28	G					YES	S
MON 385.29	G					YES	S
MON 385.30	G					YES	S
MON 386	G	R				YES	S
MON 386.1	G					YES	S
MON 386.2	G					YES	S
MON 386.3	G					YES	S
MON 386.4	G					YES	S
MON 386.5	G					YES	S
MON 387	G	R				YES	S
MON 387.1	G	R				YES	S
MON 387.2	G					YES	S
MON 387.3	G	R				YES	S
MON 387.4	G					YES	S
MON 387.5	G					YES	S
MON 387.6	G					YES	S
MON 387.7	G					YES	S
MON 387.8	G					YES	S
MON 387.9	G					YES	S
MON 387.10	G					YES	S
MON 387.11	G					YES	S
MON 387.12	G					YES	S
MON 387.13	G					YES	S
MON 387.14	G					YES	S
MON 387.15	G					YES	S
MON 387.16	G					YES	S
MON 387.17	G					YES	S
MON 387.18	G					YES	S
MON 387.19	G					YES	S

**International Boundary Commission
Joint Annual Report 2017**

***Highlands N.E. Section
(Quebec/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 387.20	G					YES	S
MON 387.21	G					YES	S
MON 387.22	G					YES	S
MON 387.23	G					YES	S
MON 387.24	G					YES	S
MON 387.25	G					NO	S
MON 387.26	G					NO	S
MON 387.27	G					NO	S
MON 388	G					NO	S
MON 388.1	G					YES	S
MON 388.2	G					YES	S
MON 388.3	G					YES	S
MON 388.4	G					YES	S
MON 388.5	G					YES	S
MON 388.6	G					YES	S
MON 388.7	G					YES	S
MON 388.8	G					YES	S
MON 388.9	G					YES	S
MON 388.10	G					YES	S
MON 389	F	R				YES	S
MON 389.1	G					YES	S
MON 389.2	G					YES	S
MON 389.3	G					YES	S
MON 389.4	G					YES	S
MON 389.5	G					YES	S
MON 389.6	G					YES	S
MON 389.7	G					YES	S
MON 389.8	G					YES	S
MON 389.9	G					YES	S
MON 389.10	G					YES	S
MON 389.11	G					YES	S
MON 389.12	G					YES	S
MON 390	G	R				YES	S
MON 390.1	G					YES	
MON 390.2	G					YES	
MON 390.3	G					YES	
MON 390.4	G					YES	
MON 390.5	G					YES	
MON 390.6	G					YES	
MON 390.7	G					YES	
MON 390.8	G					YES	
MON 390.9	G					YES	
MON 390.10	G					YES	
MON 390.11	G					YES	
MON 390.12	F					YES	

International Boundary Commission
Joint Annual Report 2017

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 390.13	P					YES	
MON 390.14	G					YES	
MON 390.15	G					YES	
MON 390.16	G					YES	
MON 391	G	R				YES	
MON 391.1	G					YES	
MON 391.2	P					YES	
MON 391.3	G					YES	
MON 391.4	G					YES	
MON 391.5	G					YES	
MON 391.6	G					YES	
MON 391.7	G					YES	
MON 392	F	R				YES	
MON 392.1	G					YES	
MON 392.2	G					YES	
MON 392.3	G					YES	
MON 392.4	G					YES	
MON 392.5	G					YES	
MON 392.6	G					YES	
MON 392.7	G					YES	
MON 392.8	G					YES	
MON 392.9	F					YES	
MON 392.10	G					YES	
MON 392.11	G					YES	
MON 392.12	F					YES	
MON 392.13	G					YES	
MON 392.14	G					YES	
MON 392.15	G					YES	
MON 392.16	G					YES	
MON 392.17	G					YES	
MON 393	D					YES	
MON 393.1	G					YES	
MON 393.2	G					YES	
MON 393.3	G					YES	
MON 393.4	P					YES	
MON 393.5	G					YES	
MON 393.6	F					YES	
MON 393.7	G					YES	
MON 393.8	G					YES	
MON 393.9	G					YES	
MON 393.10	G					YES	
MON 393.11	G					YES	
MON 393.12	G					YES	
MON 393.13	F					YES	
MON 393.14	G					YES	

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 393.15	G					YES	
MON 393.16	G					YES	
MON 394	G	R				YES	S
MON 394.1	G					YES	S
MON 394.2	NR					NO	
MON 394.3	G					YES	
MON 394.4	F					YES	
MON 394.5	F					YES	
MON 394.6	F					YES	
MON 394.7	G					YES	
MON 394.8	P					YES	
MON 394.9	P					YES	
MON 394.10	G					YES	
MON 394.11	P					YES	
MON 394.12	F					YES	
MON 394.13	G					YES	
MON 395	G	R				YES	
MON 395.1	F					YES	
MON 395.2	F					YES	
MON 395.3	F					YES	
MON 395.4	G					YES	
MON 395.5	G					YES	
MON 395.6	G					YES	
MON 395.7	F					YES	
MON 395.8	G					YES	
MON 395.9	G					YES	
MON 395.10	F					YES	
MON 395.11	G					YES	
MON 395.12	G					YES	
MON 395.13	F					YES	
MON 395.14	P					YES	
MON 395.15	G					YES	
MON 396	P	R				YES	
MON 396.1	G					YES	
MON 396.2	G					YES	
MON 396.3	G					YES	
MON 396.4	G					YES	
MON 396.5	F					YES	
MON 396.6	G					YES	
MON 396.7	G					YES	
MON 396.8	G					YES	
MON 396.9	G					YES	
MON 396.10	G					YES	
MON 396.11	G					YES	
MON 396.12	G					YES	

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 396.13	G					YES	
MON 396.14	P					YES	
MON 396.15	G					YES	
MON 396.16	P					YES	
MON 397	F	R				YES	
MON 397.1	G	R				YES	
MON 397.2	P					YES	
MON 397.3	P					YES	
MON 397.4	G					YES	
MON 397.5	G					YES	
MON 397.6	G					YES	
MON 397.7	F					YES	
MON 397.8	G					YES	
MON 397.9	F					YES	
MON 397.10	G					YES	
MON 397.11	G					YES	
MON 397.12	G					YES	
MON 397.13	G					YES	
MON 398	G	R				YES	
MON 398.1	P					YES	
MON 398.2	G					YES	
MON 398.3	G					YES	
MON 398.4	G					YES	
MON 398.5	F					YES	
MON 398.6	G					YES	
MON 398.7	F					YES	
MON 398.8	P					YES	
MON 398.9	F					YES	
MON 398.10	G					YES	
MON 398.11	F					YES	
MON 398.12	F					YES	
MON 398.13	G					YES	
MON 399	G	R				YES	
MON 399.1	G					YES	
MON 399.2	G					YES	
MON 399.3	F					YES	
MON 399.4	F					YES	
MON 399.5	P					YES	
MON 399.6	G					YES	
MON 399.7	P					YES	
MON 399.8	F					YES	
MON 399.9	F					YES	
MON 399.10	G					YES	
MON 399.11	F					YES	
MON 399.12	G					YES	

**International Boundary Commission
Joint Annual Report 2017**

***Highlands N.E. Section
(Quebec/Maine)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 400	G	R				YES	
MON 400.1	P					YES	
MON 400.2	P					YES	
MON 400.3	F					YES	
MON 400.4	F					YES	
MON 400.5	G					YES	
MON 400.6	F					YES	
MON 400.7	G					YES	
MON 400.8	F					YES	
MON 400.9	P					YES	
MON 400.10	P					YES	
MON 400.11	F					YES	
MON 400.12	G					YES	S
MON 400.13	G					YES	S
MON 400.14	G					YES	S
MON 400.15	P					YES	S
MON 400.16	P					YES	S
MON 400.17	P					YES	S
MON 400.18	F					YES	S
MON 400.19	F					YES	S
MON 400.20	P					YES	S
MON 400.21	F					YES	S
MON 401	G					YES	S
MON 401.1	F					YES	S
MON 401.2	G					YES	S
MON 401.3	F					YES	S
MON 401.4	G					YES	S
MON 401.5	G					YES	S
MON 401.6	G					YES	S
MON 401.7	G					YES	S
MON 401.8	F					YES	S
MON 401.9	D					YES	S
MON 401.10	P					YES	S
MON 401.11	G					YES	S
MON 401.12	G					YES	S
MON 401.13	G					YES	S
RM 402	NR					NO	
MON 402	G					YES	S
MON 402.1	G					YES	S
MON 402.2	G					YES	S
MON 402.3	G					YES	
MON 402.4	G					YES	
MON 402.5	G					YES	
MON 402.6	G					YES	
MON 402.7	G					YES	

International Boundary Commission
Joint Annual Report 2017

Highlands N.E. Section
(Quebec/Maine)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 402.8	G					YES	
MON 402.9	G	R				YES	
MON 402.10	G					YES	
MON 402.11	G					YES	
MON 402.12	G					YES	
MON 402.13	G					YES	
MON 402.14	G					YES	
MON 402.15	G					YES	
MON 402.16	F					YES	
MON 403	F	R				YES	
MON 403.1	G					YES	
MON 403.2	F					YES	
MON 403.3	F					YES	
MON 403.8	G	R				YES	
MON 403.9	G	R				YES	
MON 404.9	G	R				YES	
MON 404.10	G					YES	
MON 404.11	G					YES	
MON 404.12	G					YES	
MON 404.13	G					YES	
MON 404.14	G					YES	
MON 404.15	F					YES	
MON 404.16	G					YES	
MON 404.17	G	R				YES	
MON 404.18	G					YES	
MON 404.19	G					YES	
MON 404.20	G					YES	
MON 404.21	G					YES	
MON 404.22	G					YES	
MON 404.23	P					YES	
MON 404.24	F					YES	
MON 404.25	G					YES	
MON 404.26	P					YES	
MON 404.27	G					YES	

Highlands S.W. Section
(Quebec/Maine, New Hampshire)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 405	G	R				YES	
MON 429B	F					YES	
MON 429.7	G					YES	

Highlands S.W. Section
(Quebec/Maine, New Hampshire)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 429.8	G					YES	
MON 430	F					YES	
MON 430.1	G					YES	
MON 430.2	G					YES	
MON 430.3	G					YES	
MON 430.4	G					YES	
MON 430.5	G					YES	
MON 430.6	F					YES	
MON 430.7	G					YES	
MON 430.8	G					YES	
MON 431.6	G					YES	
MON 431.7	P					YES	
MON 432	G					YES	
MON 432.1	G					YES	
MON 432.2	G					YES	
MON 432.3	G					YES	
MON 432.4	F					YES	
MON 432.5	G					YES	
MON 432.6	G					YES	
MON 432.7	G					YES	
MON 432.8	G					YES	
MON 432.9	G					YES	
MON 432.10	P					YES	
MON 432.11	G					YES	
MON 434.11	G					YES	
MON 434.12	G					YES	
MON 434.13	G					YES	
MON 435	G					YES	
MON 435.1	G					YES	
MON 435.2	G					YES	
MON 435.3	G					YES	
MON 435.4	G					YES	
MON 464	G					YES	
MON 464.1	F					YES	
MON 464.2	G					YES	
MON 464.3	G					YES	
MON 464.4	G					YES	
MON 464.5	G					YES	
MON 464.6	G					YES	
MON 464.7	G					YES	
MON 464.8	G					YES	
MON 464.9	G					YES	
MON 464.10	G					YES	
MON 465	G					YES	
MON 465.1	G					YES	

**International Boundary Commission
Joint Annual Report 2017**

***Highlands S.W. Section
(Quebec/Maine, New Hampshire)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 465.2	G					YES	
MON 465.2A	G					YES	
MON 465.2B	F					YES	
MON 465.3	G					YES	
MON 465.4	G					YES	
MON 465.5	G					YES	
MON 465.5A	G					YES	
MON 465.6	G					YES	
MON 465.7	G					YES	
MON 465.8	G					YES	
MON 465.9	G					YES	
MON 465.10	G					YES	
MON 465.11	G					YES	
MON 465.12	G					YES	
MON 465.13	G					YES	
MON 465.14	G					YES	
MON 465.15	G					YES	
MON 465.16	G					YES	
MON 466	G					YES	
MON 466.1	G					YES	
MON 466.2	G					YES	
MON 466.3	G					YES	
MON 466.4	G					YES	
MON 484 (WEST POST)	G			MP		YES	
MON 484A	P			MP		YES	

***Halls Stream
(Quebec/New Hampshire)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON TP467	G					YES	
MON TP468	G					YES	
MON TP469	G					YES	
MON TP470	G					YES	
MON TP471	G					YES	
MON TP472	G					YES	
MON TP473	G					YES	
MON TP474	G					YES	
MON TP475	G					YES	
MON TP476	G					YES	
MON TP477	G					YES	
MON 478	NR					NO	

International Boundary Commission
Joint Annual Report 2017

Halls Stream
(Quebec/New Hampshire)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 479	G					YES	
MON 480	G					YES	
MON 481	G					YES	
MON 482	G					YES	
MON 483	G					NO	
MON 484	NR					NO	
MON 485	G					YES	
MON TP486	G					YES	
MON TP487	G					YES	
MON TP488	NR					NO	
MON TP489	NR					NO	
MON TP491	NR					NO	
MON TP492	G					YES	
MON 525A	G					YES	
MON TP526	G					YES	
MON TP527	G					YES	
MON TP528	G					NO	
MON TP531	G					NO	
MON TP532	G					YES	
MON TP533	G					YES	
MON TP535	G					YES	
MON TP536	G					YES	
MON TP537	G					YES	
MON TP538	G					YES	
MON TP539	NR					NO	
MON TP544	D					YES	
MON TP545	G					YES	
MON TP546	G					YES	
MON TP547	G					YES	
MON TP548	NR					NO	
MON TP549	G					YES	
MON TP550	G					YES	
MON TP551	D					NO	
MON TP552	G					YES	
MON TP554	D					YES	
MON TP555	G					YES	
MON TP556	G					YES	
MON TP557	NR					NO	
MON TP558	G					YES	
MON TP562	G					YES	
MON TP563	NR					NO	
MON TP564	G					YES	
MON TP565	G					YES	
MON TP566	G					YES	
MON TP567	NR					NO	

International Boundary Commission
Joint Annual Report 2017

Halls Stream
(Quebec/New Hampshire)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON TP571	NR					NO	
MON TP572	F					YES	
MON TP573	G					YES	
MON TP574	G					YES	
MON TP575	G					YES	
MON 580	G					YES	
MON 581	G					YES	
MON TP582	G					YES	
MON 583	G					YES	
MON 584	G					YES	
MON 585	G					YES	
MON 586	G					YES	
MON 595	G					YES	
MON 596	G					YES	
MON 597	G					YES	
MON 598	G					YES	
MON 599	G					YES	
MON 600	G					YES	
MON 601	G					YES	
MON 602	G					YES	
MON 603	G					YES	
MON 603A	D					YES	
MON 608A	D					YES	
MON TP609	G					YES	
MON TP610	G					YES	
MON TP611	G					YES	
MON TP612	D					NO	
MON 613A	D					YES	
MON TP614	G					YES	
MON 614A	G					YES	
RM 512	P			MP		NO	

West Line (QC/VT)
(Quebec/New Hampshire, Vermont)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 518	G			MP		YES	
MON 518A	G			MP		YES	
MON 519AA	G			MP		YES	
MON 519A	P			MP	DU	YES	
MON 519A2	G			MP		YES	
MON 519A3	G			MP		YES	

**International Boundary Commission
Joint Annual Report 2017**

***West Line (QC/VT)*
*(Quebec/New Hampshire, Vermont)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 519A4	G			MP		YES	
MON 520	G			MP		YES	
MON 520A	G			MP		YES	
MON 521	G			MP		YES	
MON 521A	G			MP		YES	
MON 522	G			MP		YES	
MON 522A	G			MP		YES	
MON 522A1	G			MP		YES	
MON 522A2	NR					NO	
MON 522A3	G			MP		YES	
MON 523	G			MP		YES	
MON 523A	G			MP		YES	
MON 524	G			MP		YES	
MON 525	G			MP		YES	
MON 525A	G			MP		YES	
MON 525B	G			MP		YES	
MON 526	P			MP	DU	YES	
MON 527A	G			MP		YES	
MON 527A2	G			MP		YES	
MON 528	G			MP		YES	
MON 529	G			MP		YES	
MON 530	G			MP		YES	
MON 531	G			MP		YES	
MON 531A	G			MP		YES	
MON 531B	G			MP	DU	YES	
MON 532	G			MP		YES	
MON 533	G			MP		YES	
MON 534	G			MP		YES	
MON 534A	G			MP		YES	
MON 534B	G			MP		YES	
MON 535	G			MP		YES	
MON 535AAA	G			MP		YES	
MON 535A	NR					NO	
MON 535AA	G			MP		YES	
MON 535AB	F			MP	DU	YES	
MON 535B	G			MP		YES	
MON 535C	G			MP		YES	
MON 535C1	G			MP		YES	
MON 535D	G			MP		YES	
MON 535E	G			MP		YES	
MON 535F	P			MP	DU	YES	
MON 536	G			MP		YES	
MON 537	G			MP		YES	
MON 538	G			MP		YES	
MON 538A	G			MP		YES	

**International Boundary Commission
Joint Annual Report 2017**

***West Line (QC/VT)*
*(Quebec/New Hampshire, Vermont)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 538B	G			MP		YES	
MON 538C	G			MP		YES	
MON 539	G			MP		YES	
MON 539A	G			MP		YES	
MON 540	P			MP	DU	YES	
MON 540A	F			MP	DU	YES	
MON 541	F			MP	DU	YES	
MON 542	P			MP	DU	YES	
MON 543	G			MP		YES	
MON 544	P	R		MP	DU	YES	S
MON 544B	G	NM			DU	YES	S
MON 544A	G	NM			DU	YES	S
MON 545	G	R		MP	DU	YES	S
MON 545A	F		MI	MP	DU	YES	
MON 546	G			MP		YES	
MON 546A	F			MP	DU	YES	
MON 547	P	R		MP	DU	YES	S
MON 548	G			MP		YES	
MON 548A	G			MP		YES	
MON 548B	F			MP	DU	YES	
MON 549	G			MP		YES	
MON 549A	P			MP	DU	YES	
MON 550	G			MP		YES	
MON 551	P			MP	DU	YES	
MON 551A-35	G			MP		YES	S
MON 551A1	G			MP		YES	
MON 551A2	G			MP		YES	
MON 551A3	G			MP		YES	
MON 551B	P			MP	DU	YES	
MON 552A	P	R		MP	DU	YES	S
MON 553-00	F			MP	DU	YES	
MON 553A	G			MP		YES	
MON 554W	G			MP		YES	
MON 554A	D				DU	YES	
MON 555	P			MP	DU	YES	
MON 555A	F			MP	DU	YES	
MON 555B	G			MP		YES	
MON 556A	G			MP		YES	
MON 557	G			MP		YES	
MON 557A	G			MP		YES	
MON 558	G			MP		YES	
MON 558A	G			MP		YES	
MON 560	G			MP	DU	YES	S
MON 560A	F			MP	DU	YES	
MON 561	NR					NO	

**International Boundary Commission
Joint Annual Report 2017**

***West Line (QC/VT)*
*(Quebec/New Hampshire, Vermont)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 562	G			MP		YES	
MON 562A	G			MP		YES	
MON 563	F			MP	DU	YES	
MON 563A	G			MP		YES	
MON 564	G			MP		YES	
MON 564A	G			MP		YES	
MON 565	G			MP		YES	
MON 565A	G			MP		YES	
MON 565B	G			MP		YES	
MON 566	P			MP	DU	YES	
MON 567	F			MP	DU	YES	
MON 568	G			MP		YES	
MON 569	G			MP		YES	
MON 570	P			MP	DU	YES	S
MON 572	F			MP	DU	YES	
MON 572A	G			MP		YES	
MON 573-99	G			MP		YES	
MON 573A	P			MP	DU	YES	
MON 573B	P			MP	DU	YES	
MON 574	P			MP	DU	YES	
MON 574A	F			MP	DU	YES	
MON 575	G			MP		YES	
MON 575A	F			MP	DU	YES	
MON 576	P			MP	DU	YES	
MON 577	G			MP		YES	
MON 578	G			MP		YES	
MON 579	P			MP	DU	YES	
MON 580	P			MP	DU	YES	
MON 580A	G			MP		YES	
MON 581	P			MP	DU	YES	
MON 581A	F			MP	DU	YES	
MON 581B	F			MP	DU	YES	
MON 582	P			MP	DU	YES	
MON 582A	F			MP	DU	YES	
MON 583	F			MP	DU	YES	
MON 584	F			MP	DU	YES	
MON 584A	G			MP		YES	
MON 585	G			MP		YES	
MON 586	G			MP	DU	YES	
MON 587	G			MP		YES	
MON 587A	G			MP		YES	
MON 587B	G			MP		YES	
MON 588	G			MP		YES	
MON 588A	F			MP	DU	YES	
MON 588B	F			MP	DU	YES	

**International Boundary Commission
Joint Annual Report 2017**

***West Line (QC/VT)*
*(Quebec/New Hampshire, Vermont)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 589	G			MP		YES	
MON 590	G			MP		YES	
MON 591	F			MP	DU	YES	
MON 591A	P			MP	DU	YES	
MON 591B	P			MP	DU	YES	
MON 592	P			MP	DU	YES	
MON 592A	F			MP	DU	YES	
MON 592B	G			MP		YES	
MON 593	G			MP		YES	
MON 593A	G			MP		YES	
MON 593B	G			MP		YES	
MON 594	G			MP		YES	
MON 594A	P			MP	DU	YES	
MON 594B	G			MP		YES	
MON 594C	G			MP		YES	
MON 594D	G			MP		YES	
MON 595	F			MP	DU	YES	
MON 596	P	R			DU	YES	
MON 596A	P			MP	DU	YES	
MON 596B	G		MI	MP	DU	YES	
MON 597	F			MP	DU	YES	
MON 597A	G			MP		YES	
MON 597B	F			MP	DU	YES	
MON 598	G			MP		YES	
MON 598A	F			MP	DU	YES	
MON 599	P			MP	DU	YES	
MON 599A	G			MP		YES	
MON 599B	G			MP		YES	
MON 600	NR					NO	
MON 600A	G			MP		YES	
MON 601	G			MP		YES	
MON 601A	F			MP	DU	YES	
MON 602	F			MP	DU	YES	
MON 603	F			MP	DU	YES	
MON 603A	G			MP		YES	
MON 604	F			MP	DU	YES	
MON 605	G			MP		YES	
MON 605A	G			MP		YES	
MON 605B-99	P			MP	DU	YES	
MON 606	G			MP		YES	
MON 606A	P			MP	DU	YES	
MON 607	F			MP	DU	YES	
MON 608	G			MP		YES	
MON 608A	G			MP		YES	
MON 608B	G			MP		YES	

**International Boundary Commission
Joint Annual Report 2017**

***West Line (QC/VT)*
*(Quebec/New Hampshire, Vermont)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 608C	F			MP	DU	YES	
MON 609	F			MP	DU	YES	
MON 609A	G			MP		YES	
MON 610	P			MP	DU	YES	
MON 611-59	G			MP		YES	
MON 611A	G			MP		YES	
MON 612	G			MP	DU	YES	
MON 613	G			MP		YES	
MON 614	G			MP		YES	
MON 614A	F			MP	DU	YES	
MON 614B	G			MP		YES	
MON 614C	G			MP		YES	
MON 614D	G			MP		YES	
MON 615	G			MP		YES	
MON 616	G			MP		YES	
MON 616A	G			MP		YES	
MON 616B	G			MP		YES	
MON 616C	G			MP		YES	
MON 617	G			MP		YES	
MON 618	G			MP		YES	
MON 618A	G			MP		YES	
MON 618B	P			MP	DU	YES	
MON 619	G			MP		YES	
MON 619A	G			MP		YES	
MON 619B	P			MP	DU	YES	
MON 620	G			MP		YES	
MON 620A	G			MP		YES	
MON 620B	P			MP	DU	YES	
MON 621	G			MP		YES	
MON 621W	G			MP		YES	
MON 621A	F			MP	DU	YES	
MON 621B	F			MP	DU	YES	
MON 622	F			MP	DU	YES	
MON 622A	G			MP		YES	
MON 623	G			MP		YES	
MON 624	G			MP		YES	
MON 625	G			MP		YES	
MON 625A	G			MP		YES	
MON 625B	G			MP		YES	
MON 625C	G			MP		YES	
MON 626	F			MP	DU	YES	
MON 626A	G			MP		YES	
MON 627	G			MP		YES	
MON 627A	G			MP		YES	
MON 628	G			MP		YES	

**International Boundary Commission
Joint Annual Report 2017**

***West Line (QC/VT)*
*(Quebec/New Hampshire, Vermont)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 629	P			MP	DU	YES	
MON 629A	G			MP		YES	
MON 629B	G			MP		YES	
MON 629C	G			MP		YES	
MON 629D	G			MP		YES	
MON 629E	G			MP		YES	
MON 629E1	G			MP		YES	
MON 629F	G			MP		YES	
MON 630AA	G			MP		YES	
MON 630A	G			MP		YES	
MON 630B	G			MP		YES	
MON 631	G			MP		YES	

***Lake Superior to Rainy River*
*(Ontario/Minnesota)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 357	F		MI	MP	DU	YES	
RM 361	F		MI	MP	DU	YES	
RM 365	F		MI	MP	DU	YES	
RM 375	F		MI	MP	DU	YES	
RM 376	F		MI	MP	DU	YES	
RM 383	F		MI	MP	DU	YES	
RM 388	F		MI	MP	DU	YES	
RM 413-17	G	NM		MP	DU	YES	
RM 422	F		MI	MP	DU	YES	
RM 423	F		MI	MP	DU	YES	
RM 425-17	G	NM		MP	DU	YES	
RM 428-17	G	NM		MP	DU	YES	
RM 437-17	G	NM		MP	DU	YES	
RM 440-17	G	NM		MP	DU	YES	
RM 441-17	G	NM		MP	DU	YES	
RM 442-17	G	NM		MP	DU	YES	
RM 445-17	G	NM		MP	DU	YES	
RM 451	F		MI	MP	DU	YES	
RM 458	F		MI	MP	DU	YES	
RM 463	F		MI	MP	DU	YES	
RM 464	F		MI	MP	DU	YES	
RM 472	F		MI	MP	DU	YES	
RM 502	F		MI	MP	DU	YES	
RM 508	F		MI	MP	DU	YES	
RM 513	P		MA	MP	DU	YES	

**International Boundary Commission
Joint Annual Report 2017**

**Lake Superior to Rainy River
(Ontario/Minnesota)**

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 518	F		MI	MP	DU	YES	
RM 540	F		MI	MP	DU	YES	
RM 554	F		MI	MP	DU	YES	
RM 569	F		MI	MP	DU	YES	
RM 576	F		MI	MP	DU	YES	
RM 578	F		MI	MP	DU	YES	
RM 580	F		MI	MP	DU	YES	
RM 584	F		MI	MP	DU	YES	
RM 585	F		MI	MP	DU	YES	
RM 590	F		MI	MP	DU	YES	
RM 594	F		MI	MP	DU	YES	
RM 595	F		MI	MP	DU	YES	
RM 598	F		MI	MP	DU	YES	
RM 599	F		MI	MP	DU	YES	
RM 602	F		MI	MP	DU	YES	
RM 607	F		MI	MP	DU	YES	
RM 606	F		MI	MP	DU	YES	
RM 619	G			MP	DU	YES	
RM 624	F		MI	MP	DU	YES	
RM 628	F		MI	MP	DU	YES	
RM 645	F		MI	MP	DU	YES	
RM 648	F		MI	MP	DU	YES	
RM 652	F		MI	MP	DU	YES	
RM 654	F		MI	MP	DU	YES	
RM 656	P		MA	MP	DU	YES	
RM 679	F		MI	MP	DU	YES	
RM 722	F		MI	MP	DU	YES	
RM 734	G			MP	DU	YES	
RM 758	F		MI	MP	DU	YES	
RM 764	G			MP	DU	YES	
RM 766	P		MA	MP	DU	YES	
RM 775	G			MP	DU	YES	
RM 796	G			MP	DU	YES	
RM 810	F		MI	MP	DU	YES	
RM 844	F		MI	MP	DU	YES	
RM 845	F		MI	MP	DU	YES	
RM 847	F		MI	MP	DU	YES	
RM 849	F		MI	MP	DU	YES	
RM 850	G			MP	DU	YES	
RM 851	NR				DU	NO	
RM 852	G			MP	DU	YES	
RM 854	G			MP	DU	YES	
RM 863	F		MI	MP	DU	YES	
RM 865	F		MI	MP	DU	YES	
RM 872	G			MP	DU	YES	

International Boundary Commission
Joint Annual Report 2017

Lake Superior to Rainy River
(Ontario/Minnesota)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 879	NR				DU	NO	
RM 895	P			MP	DU	YES	
RM 898	P		MA	MP	DU	YES	
RM 901	F		MI	MP	DU	YES	
RM 902	F		MI	MP	DU	YES	
RM 903	F		MI	MP	DU	YES	
RM 907	F		MI	MP	DU	YES	
RM 915	F		MI	MP	DU	YES	
RM 918	F		MI	MP	DU	YES	
RM 929	F		MI	MP	DU	YES	
RM 926	G			MP	DU	YES	
RM 935	G			MP	DU	YES	
RM 937	F		MI	MP	DU	YES	
RM 936	F		MI	MP	DU	YES	
RM 939	F		MI	MP	DU	YES	
RM 938	P			MP	DU	YES	
RM 941	F		MI	MP	DU	YES	
RM 943	P		MA	MP	DU	YES	
RM 945	P			MP	DU	YES	
RM 949	NR				DU	NO	
RM 952	G			MP	DU	YES	
RM 955	F		MI	MP	DU	YES	
RM 956	P		MA	MP	DU	YES	
RM 962	F				DU	YES	
RM 964	NR				DU	NO	
RM 972	F		MI	MP	DU	YES	
RM 977	F		MI	MP	DU	YES	
RM 978	P				DU	YES	
RM 980	NR				DU	NO	
RM 984	NR				DU	NO	
RM 991	G			MP	DU	YES	
RM 1010	F		MI	MP	DU	YES	
RM 1015	F		MI	MP	DU	YES	
RM 1014	F		MI	MP	DU	YES	
RM 1035	G				DU	YES	
RM 1037	NR				DU	NO	
RM 1059	NR				DU	NO	
RM 1073	P				DU	YES	
RM 1066	G			MP	DU	YES	
RM 1077	G			MP	DU	YES	
RM 1079	G			MP	DU	YES	
RM 1081	G			MP	DU	YES	
RM 1072	G			MP	DU	YES	
RM 1068	G			MP	DU	YES	
RM 1097	NR				DU	NO	

International Boundary Commission
Joint Annual Report 2017

Lake Superior to Rainy River
(Ontario/Minnesota)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 1108	NR				DU	NO	
RM 1112	F		MI	MP	DU	YES	
RM 1114	P				DU	YES	
RM 1116	NR				DU	NO	
RM 1122	P				DU	YES	
RM 1128	G			MP	DU	YES	
RM 1131	F		MI	MP	DU	YES	
RM 1137	P		MA	MP	DU	YES	
RM 1144	P				DU	YES	
RM 1146	P				DU	YES	
RM 1148	P				DU	YES	
RM 1151	NR				DU	NO	
RM 1152	P				DU	YES	
RM 1160	F				DU	YES	
RM 1168	P		MA	MP	DU	YES	
RM 1198	P		MA	MP	DU	YES	
RM 1202	F				DU	YES	
RM 1211	G			MP	DU	YES	
RM 1206	G			MP	DU	YES	
RM 1217	F		MI	MP	DU	YES	
RM 1223	P				DU	YES	
RM 1225	G			MP	DU	YES	
RM 1227	P				DU	YES	
RM 1220	F				DU	YES	
RM 1229	P				DU	YES	
RM 1231	P				DU	YES	
RM 1222	F		MI	MP	DU	YES	
RM 1235	P				DU	YES	
RM 1239	P				DU	YES	
RM 1224	P				DU	YES	
RM 1241	P				DU	YES	
RM 1226	F				DU	YES	
RM 1243	P				DU	YES	
RM 1228	P				DU	YES	
RM 1247	F				DU	YES	
RM 1234	P				DU	YES	
RM 1236	P				DU	YES	
RM 1249	P				DU	YES	
RM 1257	NR				DU	NO	
RM 1261	NR				DU	NO	
RM 1246	P				DU	YES	
RM 1248	P				DU	YES	
RM 1263	NR				DU	NO	
RM 1252	P				DU	YES	
RM 1267	G			MP	DU	YES	

International Boundary Commission
Joint Annual Report 2017

Lake Superior to Rainy River
(Ontario/Minnesota)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 1269	NR				DU	NO	
RM 1254	NR				DU	NO	
RM 1258	G			MP	DU	YES	
RM 1281	NR				DU	NO	
RM 1283	NR				DU	NO	
RM 1266	F		MI	MP	DU	YES	
RM 1285	F				DU	YES	
RM 1270	NR				DU	NO	
RM 1291	F				DU	YES	
RM 1276	P		MA	MP	DU	YES	
RM 1280	F		MI	MP	DU	YES	
RM 1282	F		MI	MP	DU	YES	
RM 1284	F		MI	MP	DU	YES	
RM 1284-A	NR				DU	NO	
RM 1294	G			MP	DU	YES	
RM 1298	G			MP	DU	YES	
RM 1304	F		MI	MP	DU	YES	
RM 421-17	G	NM		MP	DU	YES	

Rainy River and Lake of the Woods
(Ontario/Minnesota)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 17	P		MA	MP	DU	YES	
RM 18	P		MA	MP	DU	YES	
RM 21	P		MA	MP	DU	YES	
RM 23	P		MA	MP	DU	YES	
RM 27	P		MA	MP	DU	YES	
RM 29	P		MA	MP	DU	YES	
RM 33	P		MA	MP	DU	YES	
RM 68-68	P		MA	MP	DU	YES	
RM 65	P		MA	MP	DU	YES	
RM 76	P		MA	MP	DU	YES	
RM 79-68	P		MA	MP	DU	YES	
RM 83-95	P		MA	MP	DU	YES	
RM 96-68	P		MA	MP	DU	YES	
RM 163	F		MI	MP	DU	YES	
RM 165-69	P		MA	MP	DU	YES	
RM 171-37	P		MA	MP	DU	YES	
RM 172	P		MA	MP	DU	YES	
RM 179	P		MA	MP	DU	YES	
RM 191	F		MI	MP	DU	YES	

International Boundary Commission
Joint Annual Report 2017

Rainy River and Lake of the Woods
(Ontario/Minnesota)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
RM 200	P		MA	MP	DU	YES	
RM 233	F		MI	MP	DU	YES	
RM 242	F		MI	MP	DU	YES	
RM 249	F		MI	MP	DU	YES	
RM 264	F		MI	MP	DU	YES	
RM 267	F		MI	MP	DU	YES	
RM 270	F		MI	MP	DU	YES	
RM 272	F		MI	MP	DU	YES	
RM 274	F		MI	MP	DU	YES	
RM 278	F		MI	MP	DU	YES	
RM 280	F		MI	MP	DU	YES	
RM 281	F		MI	MP	DU	YES	
RM 285	F		MI	MP	DU	YES	
RM 287	F		MI	MP	DU	YES	
RM 288	F		MI	MP	DU	YES	
RM 292	F		MI	MP	DU	YES	
RM 295	F		MI	MP	DU	YES	
RM 298	F		MI	MP	DU	YES	
RM 304	F		MI	MP	DU	YES	
RM 306	F		MI	MP	DU	YES	
RM 307	F		MI	MP	DU	YES	
RM 308	F		MI	MP	DU	YES	
RM 311	F		MI	MP	DU	YES	
RM 312	F		MI	MP	DU	YES	
RM 313	F		MI	MP	DU	YES	
RM 315	F		MI	MP	DU	YES	
RM 316	F		MI	MP	DU	YES	
RM 323	F		MI	MP	DU	YES	
RM 332	P		MA	MP	DU	YES	
RM 336	F		MI	MP	DU	YES	
RM 338	F		MI	MP	DU	YES	
RM 339	F		MI	MP	DU	YES	
RM 340	F		MI	MP	DU	YES	
RM 352	F		MI	MP	DU	YES	

49th Parallel (AB-SK-MB/MT- ND)
(Alberta/Montana)

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 290	G			MP	DU	YES	
MON 290A	G			MP	DU	YES	
MON 290B	G			MP	DU	YES	

**International Boundary Commission
Joint Annual Report 2017**

**49th Parallel (AB-SK-MB/MT- ND)
(Alberta/Montana)**

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 306	G			MP	DU	YES	
MON 307	G			MP	DU	YES	
MON 308	G			MP	DU	YES	
MON 308A	G			MP	DU	YES	
MON 308B	G			MP	DU	YES	
MON 309	G			MP	DU	YES	
LM 309A	G			MP	DU	YES	
LM 309B	G			MP	DU	YES	
MON 310	G			MP	DU	YES	

**49th Parallel (Foothills to West Kootenay River)
(British Columbia, Alberta/Idaho, Montana)**

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 216A-90	G					NO	
MON 216B	NR					NO	
MON 216C	G					YES	
MON 216D	U	NM				YES	
MON 217	G					NO	
MON 281A	G		MI	MP	DU	YES	
MON 281B-66	P		MA	MP	DU	YES	
MON 282	G			MP	DU	YES	
MON 283	G			MP	DU	YES	
MON 284	G			MP	DU	YES	
MON 285	G			MP	DU	YES	
MON 286	G			MP	DU	YES	
MON 287	P		MA	MP	DU	YES	
MON 288	G			MP	DU	YES	
MON 289	G			MP	DU	YES	

**49th Parallel (Columbia Valley to Similkameen River)
(British Columbia/Washington)**

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 69	G					NO	
MON 70	NR					NO	
MON 71	P					NO	
MON 72	G					NO	
MON 73	G					NO	

**International Boundary Commission
Joint Annual Report 2017**

***49th Parallel (Columbia Valley to Similkameen River)
(British Columbia/Washington)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 74	G					NO	
MON 75	G					NO	
MON 76	G					NO	
MON 77	G					NO	
MON 78	P		MI	MP	DU	YES	
MON 79	G					NO	
MON 80	G					NO	
MON 81	G					NO	

***141st Meridian (YK/AK)
(Yukon/Alaska)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 1-83	F				DU	YES	S
MON 1A	G					YES	S
MON 2	F				DU	YES	S
MON 3	F				DU	YES	S
MON 4	G					YES	S
MON 5	G					YES	S
MON 6	P				DU	YES	S
MON 7	P				DU	YES	S
MON 8	F				DU	YES	S
MON 9	G				DU	YES	S
MON 10	F				DU	YES	S
MON 11	P				DU	YES	S
MON 12	P				DU	YES	S
MON 13	P				DU	YES	S
MON 14	G				DU	YES	S
MON 15	F				DU	YES	S
MON 16	F				DU	YES	S
MON 17	P				DU	YES	S
MON 18	G				DU	YES	S
MON 19	P				DU	YES	S
MON 20	F				DU	YES	S
MON 21	F				DU	YES	S
MON 22	F				DU	YES	S
MON 23	F				DU	YES	S
MON 24	F				DU	YES	S
MON 25	G					YES	S
MON 26	P				DU	YES	S
MON 27	P				DU	YES	S
MON 28	F				DU	YES	S

**International Boundary Commission
Joint Annual Report 2017**

**141st Meridian (YK/AK)
(Yukon/Alaska)**

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 29	P				DU	YES	S
MON 30	P				DU	YES	S
MON 31	P				DU	YES	S
MON 32-73	F				DU	YES	S
MON 33	G					YES	S
MON 34	F				DU	YES	S
MON 35	P				DU	YES	S
MON 36	G					YES	S
MON 37	P				DU	YES	S
MON 38	P				DU	YES	S
MON 38A	P				DU	YES	S
MON 39-84	F			MP	DU	YES	S
MON 40	G			MP		YES	S
MON 41	G			MP		YES	S
MON 42	G			MP		YES	S
MON 43	G			MP	DU	YES	S
MON 44	G			MP		YES	S
MON 45	G			MP		YES	S
MON 46	G			MP		YES	S
MON 46A	G			MP	DU	YES	S
MON 47	G			MP		YES	S
MON 47A	G			MP		YES	S
MON 48	G			MP		YES	S
MON 48A	G			MP		YES	S
MON 49	G			MP	DU	YES	S
MON 49A	F			MP	DU	YES	S
MON 50	G			MP		YES	S
MON 51	P				DU	YES	S
MON 52	F			MP	DU	YES	S
MON 53	P			MP	DU	YES	S
MON 54	G			MP		YES	S
MON 55	G			MP		YES	S
MON 56	P				DU	YES	S
MON 57	P			MP	DU	YES	S
MON 58	G			MP		YES	S
MON 59	F			MP	DU	YES	S
MON 60	G			MP		YES	S
MON 61	F			MP	DU	YES	S
MON 62	F			MP	DU	YES	S
MON 63	G			MP		YES	S
MON 64	G					YES	S
MON 65	F				DU	YES	S
MON 66	F				DU	YES	S
MON 67	F				DU	YES	S
MON 68	G					YES	S

**International Boundary Commission
Joint Annual Report 2017**

***141st Meridian (YK/AK)
(Yukon/Alaska)***

Boundary Monument Type & Number	Reconnaissance	Established	Repairs	Painted	Description	Photo	Monument Surveyed
MON 69	G				DU	YES	S
MON 70	G				DU	YES	S
MON 71	F					YES	S
MON 72	F				DU	YES	S
MON 73	P				DU	YES	S
MON 74	F				DU	YES	S
MON 75	F				DU	YES	S
MON 76	G			MP		YES	S
MON 77	P			MP	DU	YES	S
MON 78	F			MP	DU	YES	S
MON 79	G			MP		YES	S
MON 80	P			MP	DU	YES	S
MON 115A	G					NO	S
MON 133	G					YES	S
MON 134	P				DU	YES	S
MON 136	G					YES	S
MON 150	P				DU	YES	S
MON 189	NR					NO	
MON 191	G					YES	
MON 191A	NR					NO	

International Boundary Commission
Joint Annual Report 2017

MONUMENT MAINTENANCE

Passamaquoddy Bay
(New Brunswick/Maine)

Range Marks recovered	49
-----------------------	----

North Line
(New Brunswick/Maine)

Monuments recovered	4
Monuments painted	4

Saint John River
(New Brunswick/Maine)

Reference Monuments recovered	305
Reference Monuments not recovered	23
Reference Monuments repaired or re-established	10
Reference Monuments painted	145
Reference Monuments photographed	191
Reference Monuments surveyed	30

St. Francis River
(New Brunswick/Maine)

Reference Monuments recovered	3
Reference Monuments not recovered	1
Reference Monuments repaired or re-established	2
Reference Monuments painted	3
Reference Monuments surveyed	3

Southwest Branch of the St. John River
(New Brunswick, Quebec/Maine)

Reference Monuments recovered	9
Reference Monuments surveyed	9

Highlands N.E. Section

(Quebec/Maine)

Monuments recovered	723
Monuments not recovered	1
Monuments repaired or re-established	58
Monuments painted	1
Monuments photographed	590
Monuments surveyed	323
Reference Monuments not recovered	1

Highlands S.W. Section

(Quebec/Maine, New Hampshire)

Monuments recovered	73
Monuments repaired or re-established	1
Monuments painted	2
Monuments photographed	7

Halls Stream

(Quebec/New Hampshire)

Monuments recovered	76
Monuments not recovered	11
Monuments not photographed	71
Reference Monuments recovered	1
Reference Monuments painted	1

West Line (QC/VT)

(Quebec/New Hampshire, Vermont)

Monuments recovered	239
Monuments not recovered	4
Monuments established	2
Monuments repaired or re-established	7
Monuments painted	235
Monuments photographed	239
Monuments surveyed	9

Lake Superior to Rainy River
(Ontario/Minnesota)

Reference Monuments recovered	156
Reference Monuments not recovered	21
Reference Monuments established	9
Reference Monuments repaired or re-established	85
Reference Monuments painted	124
Reference Monuments photographed	157

Rainy River and Lake of the Woods
(Ontario/Minnesota)

Reference Monuments recovered	53
Reference Monuments repaired or re-established	53
Reference Monuments painted	53
Reference Monuments photographed	53

49th Parallel (AB-SK-MB/MT- ND)
(Alberta/Montana)

Monuments recovered	10
Monuments painted	10
Monuments photographed	10
Line Marks recovered	2
Line Marks painted	2
Line Marks photographed	2

49th Parallel (Foothills to West Kootenay River)
(British Columbia, Alberta/Idaho, Montana)

Monuments recovered	13
Monuments not recovered	1
Monuments established	1
Monuments repaired or re-established	3
Monuments painted	10
Monuments photographed	12

**International Boundary Commission
Joint Annual Report 2017**

**49th Parallel (Columbia Valley to Similkameen River)
(British Columbia/Washington)**

Monuments recovered	12
Monuments not recovered	1
Monuments repaired or re-established	1
Monuments painted	1
Monuments photographed	1

**141st Meridian (YK/AK)
(Yukon/Alaska)**

Monuments recovered	92
Monuments not recovered	2
Monuments painted	32
Monuments photographed	91
Monuments surveyed	91

VISTA MAINTENANCE

**North Line
(New Brunswick/Maine)**

Vista cleared at Houlton/Woodstock POE	
Total distance km	0,6
Total distance miles	0.4

**Highlands S.W. Section
(Quebec/Maine)**

Vista cleared between monuments 405 et 452	
Total distance km	69,9
Total distance miles	43.4

**West Line (QC/VT)
(Quebec/New Hampshire, Vermont)**

Vista cleared upon request of DHS	
Total distance km	16,4
Total distance miles	10.2

**International Boundary Commission
Joint Annual Report 2017**

**49th Parallel (AB-SK-MB/MT- ND)
(Alberta/Montana)**

Vista cleared between monuments 283 and 321

Total distance km	20,1
Total distance miles	12.5

**International Boundary Commission
Joint Annual Report 2017**

APPENDIX B – SUMMARY OF MAINTENANCE AND SURVEY WORK

**International Boundary Commission
Joint Annual Report 2017**

Summary of maintenance and survey work

Range Marks recovered	49
Monuments recovered	1,242
Reference monuments recovered	526
Monuments established	3
Reference monuments established	9
Monuments repaired/ re-established	80
Reference monuments repaired/ re-established	150
Reference monuments surveyed	42
Monuments surveyed	423
Vista cleared	107,0 km (66.5 miles)

**International Boundary Commission
Joint Annual Report 2017**

APPENDIX C – 15 YEAR PLAN

**International Boundary Commission
Joint Annual Report 2017**

International Boundary Commission
Joint Annual Report 2017

Level	Major Task	Section	Cycle (years)
3	Vista Clearing & Maintenance	Passamaquoddy Bay	3
3	Inspection & Maintenance	St. Croix River	8
1	Vista Clearing & Maintenance	North Line	6
3	Inspection & Maintenance	Saint John River	8
2	Inspection & Maintenance	St. Francis River	4
2	Vista Clearing & Maintenance	Southwest and South Lines	6
3	Inspection & Maintenance	Southwest Branch of the St. John River	8
2	Vista Clearing & Maintenance	Highlands N.E. Section	6
2	Vista Clearing & Maintenance	Highlands S.W. Section	6
2	Inspection & Maintenance	Halls Stream	4
1	Vista Clearing & Maintenance	West Line (QC/VT)	6
1	Vista Clearing & Maintenance	West Line (QC/NY)	6
3	Inspection & Maintenance	St. Lawrence River	8
3	Inspection & Maintenance	Lake Ontario and Niagara River	8
3	Inspection & Maintenance	Lake Erie, Detroit and St. Clair Rivers	8
3	Inspection & Maintenance	Lake Huron, Saint Marys River and Lake Superior	8
3	Inspection & Maintenance	Lake Superior to Rainy River	8
3	Inspection & Maintenance	Rainy River and Lake of the Woods	8
2	Vista Clearing & Maintenance	Meridian and 49th Parallel (MB/MN)	5
2	Vista Clearing & Maintenance	49th Parallel (MB/ND)	5
2	Vista Clearing & Maintenance	49th Parallel (AB-SK-MB/MT- ND)	5
3	Vista Clearing & Maintenance	49th Parallel (Foothills to West Kootenay River)	8
3	Vista Clearing & Maintenance	49th Parallel (Similkameen River to West Kootenay River)	8
3	Vista Clearing & Maintenance	49th Parallel (Columbia Valley to Similkameen River)	8
1	Vista Clearing & Maintenance	49th Parallel (Pacific to Columbia Valley)	5
3	Inspection & Maintenance	Straits of Georgia and Juan De Fuca	8
3	Inspection & Maintenance	Portland Canal	8
3	Vista Clearing & Maintenance	Southeast Alaska	10
3	Vista Clearing & Maintenance	141st Meridian (YK/AK)	15

**International Boundary Commission
Joint Annual Report 2017**

Task	Section	x 1000\$
2017	Inspection & Maintenance	Passamaquoddy Bay
	Inspection & Maintenance	Saint John River
	Inspection & Maintenance	Highlands S.W. Section
	Vista Clearing	Highlands S.W. Section
	Inspection & Maintenance	West Line (QC/VT)
	Inspection & Maintenance	Lake Superior to Rainy River
	Inspection & Maintenance	Rainy River and Lake of the Woods
	Inspection & Maintenance	49th Parallel (AB-SK-MB/MT- ND)
	Survey	49th Parallel (Foothills to West Kootenay River)
	Maintenance	49th Parallel (Pacific to Columbia Valley)
	Vista Clearing	Southeast Alaska
	Survey	141st Meridian (YK/AK)
	Mapping	
	Contingency	
	TOTAL	1,866

Task	Section	x 1000\$
2018	Vista Clearing	North Line
	Inspection & Maintenance	Saint John River
	Inspection & Maintenance	St. Francis River
	Vista Clearing	Southwest and South Lines
	Inspection & Maintenance	Southwest Branch of the St. John River
	Maintenance	Highlands N.E. Section
	Vista Clearing	Highlands S.W. Section
	Inspection & Maintenance	Halls Stream
	Vista Clearing	West Line (QC/NY)
	Inspection & Maintenance	Lake Ontario and Niagara River
	Inspection	Meridian and 49th Parallel (MB/MN)
	Maintenance	49th Parallel (AB-SK-MB/MT- ND)
	Inspection & Maintenance	49th Parallel (Pacific to Columbia Valley)
	Vista Clearing	Southeast Alaska
	Mapping	
	Contingency	
	TOTAL	2,206

**International Boundary Commission
Joint Annual Report 2017**

Task	Section	x 1000\$
2019	Inspection & Maintenance	St. Croix River
	Inspection & Maintenance	North Line
	Maintenance	Highlands N.E. Section
	Vista Clearing	West Line (QC/VT)
	Inspection & Maintenance	St. Lawrence River
	Inspection & Maintenance	Lake Erie, Detroit and St. Clair Rivers
	Vista Clearing	Meridian and 49th Parallel (MB/MN)
	Maintenance	49th Parallel (MB/ND)
	Vista Clearing	49th Parallel (MB/ND)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	49th Parallel (Similkameen River to West Kootenay River)
	Vista Clearing	49th Parallel (Pacific to Columbia Valley)
	Vista Clearing	Southeast Alaska
	Mapping	
	Contingency	
	TOTAL	2,091

Task	Section	x 1000\$
2020	Maintenance	Passamaquoddy Bay
	Maintenance	St. Croix River
	Maintenance	North Line
	Vista Clearing	Highlands N.E. Section
	Vista Clearing	West Line (QC/VT)
	Inspection & Maintenance	Lake Huron, Saint Marys River and Lake Superior
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	49th Parallel (Similkameen River to West Kootenay River)
	Vista Clearing	49th Parallel (Columbia Valley to Similkameen River)
	Inspection & Maintenance	49th Parallel (Pacific to Columbia Valley)
	Inspection & Maintenance	Straits of Georgia and Juan De Fuca
	Vista Clearing	Southeast Alaska
	Maintenance	Southeast Alaska
	Capital	Truck replacement
	Contingency	
	TOTAL	2,208

**International Boundary Commission
Joint Annual Report 2017**

Task	Section	x 1000\$
2021	Maintenance	Highlands S.W. Section
	Vista Clearing & Maintenance	Meridian and 49th Parallel (MB/MN)
	Vista Clearing	49th Parallel (MB/ND)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing & Maintenance	49th Parallel (Pacific to Columbia Valley)
	Inspection & Maintenance	Portland Canal
	Vista Clearing & Maintenance	Southeast Alaska
	Contingency	
	TOTAL	2,154

Task	Section	x 1000\$
2022	Inspection & Maintenance	St. Francis River
	Vista Clearing	Highlands N.E. Section
	Maintenance	Highlands S.W. Section
	Inspection & Maintenance	Halls Stream
	Maintenance	Meridian and 49th Parallel (MB/MN)
	Maintenance	49th Parallel (AB-SK-MB/MT- ND)
	Maintenance	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	49th Parallel (Similkameen River to West Kootenay River)
	Contingency	
	TOTAL	2,064

Task	Section	x 1000\$
2023	Survey	Passamaquoddy Bay
	Maintenance	Passamaquoddy Bay
	Survey	St. Croix River
	Vista Clearing & Maintenance	Southwest and South Lines
	Vista Clearing & Maintenance	Highlands S.W. Section
	Vista Clearing	West Line (QC/NY)
	Maintenance	Meridian and 49th Parallel (MB/MN)
	Vista Clearing & Maintenance	49th Parallel (Foothills to West Kootenay River)
	Maintenance	49th Parallel (Similkameen River to West Kootenay River)
	Contingency	
	TOTAL	1,943

Task	Section	x 1000\$
-------------	----------------	-----------------

**International Boundary Commission
Joint Annual Report 2017**

2024	Vista Clearing	North Line	90
	Vista Clearing	Highlands S.W. Section	250
	Vista Clearing	West Line (QC/VT)	110
	Vista Clearing	Meridian and 49th Parallel (MB/MN)	250
	Maintenance	49th Parallel (MB/ND)	184
	Vista Clearing & Maintenance	141st Meridian (YK/AK)	750
	Vista Clearing & Maintenance	141st Meridian (YK/AK)	500
	Contingency		50
	TOTAL		2,184

Task	Section	x 1000\$
2025	Vista Clearing & Maintenance	North Line
	Vista Clearing	West Line (QC/VT)
	Maintenance	St. Lawrence River
	Maintenance	Lake Superior to Rainy River
	Maintenance	Rainy River and Lake of the Woods
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing & Maintenance	49th Parallel (Columbia Valley to Similkameen River)
	Vista Clearing & Maintenance	49th Parallel (Pacific to Columbia Valley)
	Vista Clearing	141st Meridian (YK/AK)
	Vista Clearing	141st Meridian (YK/AK)
	Contingency	50
	TOTAL	2,433

Task	Section	x 1000\$
2026	Vista Clearing & Maintenance	Passamaquoddy Bay
	Vista Clearing & Maintenance	North Line
	Maintenance	Saint John River
	Maintenance	St. Francis River
	Maintenance	Southwest Branch of the St. John River
	Inspection & Maintenance	Halls Stream
	Maintenance	Lake Ontario and Niagara River
	Vista Clearing	Meridian and 49th Parallel (MB/MN)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	141st Meridian (YK/AK)
	Vista Clearing	141st Meridian (YK/AK)
	Contingency	50
	TOTAL	2,632

**International Boundary Commission
Joint Annual Report 2017**

Task	Section	x 1000\$
2027	Maintenance	St. Croix River
	Maintenance	Lake Erie, Detroit and St. Clair Rivers
	Vista Clearing	Meridian and 49th Parallel (MB/MN)
	Inspection & Maintenance	49th Parallel (AB-SK-MB/MT- ND)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing & Maintenance	49th Parallel (Similkameen River to West Kootenay River)
	Vista Clearing	141st Meridian (YK/AK)
	Vista Clearing	141st Meridian (YK/AK)
	Contingency	
	TOTAL	2,232

Task	Section	x 1000\$
2028	Maintenance	St. Croix River
	Vista Clearing & Maintenance	Southwest and South Lines
	Vista Clearing	Highlands N.E. Section
	Vista Clearing & Maintenance	West Line (QC/NY)
	Inspection & Maintenance	Lake Huron, Saint Marys River and Lake Superior
	Vista Clearing & Maintenance	Meridian and 49th Parallel (MB/MN)
	Vista Clearing & Maintenance	49th Parallel (MB/ND)
	Maintenance	49th Parallel (AB-SK-MB/MT- ND)
	Vista Clearing & Maintenance	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing	141st Meridian (YK/AK)
	Contingency	
	TOTAL	2,643


Task	Section	x 1000\$
2029	Vista Clearing & Maintenance	Passamaquoddy Bay
	Vista Clearing	Highlands S.W. Section
	Vista Clearing	West Line (QC/VT)
	Vista Clearing	Meridian and 49th Parallel (MB/MN)
	Vista Clearing & Maintenance	49th Parallel (MB/ND)
	Vista Clearing	49th Parallel (Foothills to West Kootenay River)
	Vista Clearing & Maintenance	49th Parallel (Columbia Valley to Similkameen River)
	Inspection & Maintenance	Portland Canal
	Vista Clearing & Maintenance	Southeast Alaska
	Contingency	
	TOTAL	2,140

International Boundary Commission
Joint Annual Report 2017

2030

Task	Section	x 1000\$
Vista Clearing & Maintenance	North Line	300
	St. Francis River	80
	West Line (QC/VT)	110
	Halls Stream	75
	49th Parallel (Foothills to West Kootenay River)	50
	49th Parallel (Pacific to Columbia Valley)	300
	Southeast Alaska	400
	Southeast Alaska	420
	Contingency	50
	TOTAL	1,785

APPENDIX D – PLANS OF MONUMENTS INSTALLED



BOUNDARY MONUMENT ESTABLISHED
BORNE FRONTIÈRE POSÉE

MON 545, 544A & 544B

IBC SECTION
West Line (QC/VT)

SECTION CFI
Ligne Ouest (QC/VT)

LOCATION
Barnston, QC
Holland, VT

LOCALISATION

Scale 1:20,000

200 0 200 400 600 800 1000 m

LEGEND

Newly established monument □ Nouvelle borne posée

Existing monument ■ Borne existante

International Boundary — Frontière internationale

LÉGENDE

Nouvelle borne posée

Borne existante

Frontière internationale

NOTES

MON 544 - Found level, solid-base is deteriorating; Renewed in original position using new standard granite obelisk.

MON 544A - New standard granite obelisk set in concrete base on line.

MON 544B - New standard granite obelisk set in concrete base on line.

MON 545 - Found top displaced, base deteriorating - lower level concrete base in place - Reset 0.25N, 0.20E and on production of MON 546 to MON 545A. Set new standard granite obelisk in concrete base. Renewed 2017.

MON 545A - Found small obelisk leaning east +/- 0.05 - Renewed 2000.

MON 546 - Found good condition, cast iron obelisk in a base - Renewed 2000.

Encroachments:

- 4' high page-wire farm fence extending along boundary east and west of MON 545.
- Snowmobile trail on Canadian side in vicinity of MON 544A.

MONUMENTED & SURVEYED BY
Joseph L. Harrietha, C.L.S
Canadian Section

ARPENTÉE ET BORNÉE PAR
International Boundary Commission
Commission de la frontière internationale

DATE OF SURVEY
September 2017

DATE DE L'ARPENTAGE
septembre 2017

INTERNATIONAL BOUNDARY COMMISSION
COMMISSION DE LA FRONTIÈRE INTERNATIONALE



**International Boundary Commission,
United States and Canada**

**Joint Annual Report
2017**